



Bulletin No.: PIP5546
Published date: N/A

Preliminary Information

PIP5546 GF9 Transmission Shudder Under 40 MPH

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Traverse	2018	All	All	All	M3V
Buick	Enclave	2018	All	All	All	M3W
Involved Region or Country	North America					
Condition	Slight shudder felt at speeds 40 MPH or below during a shift					
Cause	Possible TCC shudder on re-apply after a shift.					

Correction:

If confirmed to be a TCC shudder while monitoring TCC slip speed during the concern, or concern goes away when TCC is commanded on with the scan tool, and the concern is 40 MPH or below, perform a trans fluid drain and fill, and perform a cooler flow to flush the cooler.

A minimum of 200 miles should be driven after the drain and fill to confirm repairs.

If above 40 MPH, TSB [17-NA-317](#) should be reviewed.

This concern continues to be investigated and this PI will be updated or advanced to a bulletin, if needed.

Version History

Version	1
Modified	



© 2016 General Motors. All Rights Reserved.