

Subject: VOICE RECOGNITION SYSTEM DOES NOT RECOGNIZE "ADDRESS" OR "NEW DESTINATION" NAVIGATION VOICE COMMANDS	Bulletin No.: 09-003/18
	Last Issued: 01/10/2018

APPLICABLE MODEL(S)/VINS

2018 Mazda3 (Japan built) vehicles equipped with navigation and built between September 11, 2017 through December 5, 2017

2018 Mazda3 (Mexico built) vehicles equipped with navigation and built between March 31, 2017 through January 3, 2018

2017 Mazda6 equipped with navigation and built between September 11, 2017 through December 5, 2017

2018 CX-3 equipped with navigation and built between September 11, 2017 through December 5, 2017

2017 CX-5 equipped with navigation and built between September 11, 2017 through December 5, 2017

2018 CX-9 equipped with navigation and built between September 11, 2017 through December 5, 2017

2018 MX-5 equipped with navigation and built between September 11, 2017 through December 5, 2017

APPLICABLE SERVICE PARTS (SD card purchased by the customer)

2017-2018 Mazda3 (Japan built) vehicles with SD card purchased after June 27, 2016

2018 Mazda3 (Mexico built) vehicles with SD card purchased after September 22, 2016

2017 Mazda6 with SD card purchased after June 13, 2016

2016-2018 CX-3 with SD card purchased after March 09, 2015

2017 CX-5 with SD card purchased after December 27, 2016

2016-2018 CX-9 SD card purchased after February 11, 2016

2016-2018 MX-5 SD card purchased after April 20, 2015

DESCRIPTION

Some customers may complain that the Voice Recognition system does not recognize "Address" or "New Destination" navigation voice commands. This may be caused by faulty navigation SD card software. The SD card has been updated to eliminate this concern.



Customers having this concern should have their vehicle repaired using the following repair procedure.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

REPAIR PROCEDURE

CAUTION: NEVER swap the navigation system SD card from one vehicle to another for testing. If swapped, the SD card that is installed into the other vehicle may be “linked” to the VIN of that vehicle.

1. Verify customer concern.
2. Remove the Navigation SD Card and check the part number.




Is the part number BHP1-66-EZ1G?

- Yes - Go to next step.
- No - This TSB does not apply. Refer to MGSS online for normal diagnosis procedures.

3. Using Mazda Toolbox, open the "Device History" screen and check the SD Card version.

NOTE:

- When checking or updating a customer's vehicle SD card, the dealer technician must create his/her own Mazda Toolbox account. The Mazda Toolbox program may send a confirmation to the technician's email. For this reason, dealer technicians should NOT use the customer's account.
- Dealer checking or updating a customer's SD card will not affect the customer's free 3 year map updates.



Is the SD Card version before July 2017?

- Yes - Update Navigation SD card to the latest software using Mazda Toolbox.
- No - This service information does not apply. Refer to MGSS online for normal diagnosis procedures.

4. Verify repair.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda’s New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	64
Damage Code	9W
Part Number Main Cause	BHP1-66-EZ1G
Quantity	0
Operation Number / Labor Hours:	XXN9XXFX / 0.2 Hrs. (SD Card update)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.