

Technical Information

Service

142/17 ENU 4271

4

Noise Symptom - Creaking From Rear End Area: Checking rear spring strut for damage (SY 142/17)

Model Line: 911 Carrera/S/4/4S/GTS (991)

911/S/4/4S/GTS Cabriolet (991)

911 Targa 4/4S/GTS (991)

911 Turbo/S Coupe/Cabriolet (991)

Model Year: As of 2017 up to 2018

Subject: Rear supporting mount

Symptom: Creaking noise from chassis area at the rear of the vehicle.

Cause: The spring force of the coil spring may be outside of the tolerance range.

The increased transverse force as a result of this can overload the insert in the supporting mount.

The piston rod may no longer be guided in centrally and touches against the supporting mount housing.

 \Rightarrow This produces the metallic noise.

Remedial Action:

Before doing any other work, the following components must be checked for damage:

- Coil spring,
- · shock absorber,
- · supporting mount and
- insert.

 \Rightarrow If the piston rod has already caused damage, the inserts, supporting mounts and coil springs at the rear must be replaced in pairs. The shock absorbers may or may not need to be replaced, depending on the mileage.


Work Procedure: 1

Disassemble the affected rear spring strut. \Rightarrow Workshop Manual '427137 Disassembling and assembling rear spring strut'

2 Check insert (⇒ Overview of rear spring strut-2-), supporting mount (⇒ Overview of rear spring strut-3-), coil spring (⇒ Overview of rear spring strut-9-) and shock absorber (⇒ Overview of rear spring strut-12-) for damage.


4271

2.1 Check insert (\Rightarrow Damaged insert -2-) for damage in area \Rightarrow Damaged insert -A-.




Damaged insert

2.2 Check supporting mount (⇒ Damaged supporting mount -3-) for damage in area ⇒ Damaged supporting mount -A-.




Damaged supporting mount

2.3 Check coil spring (⇒ Damaged coil spring
-9-) for damage in area ⇒ Damaged coil spring -A-.



Damaged coil spring


2.4 Check shock absorber (⇒ Damaged shock absorber -12-) for damage in area ⇒ Damaged shock absorber -A-.



Damaged shock absorber

4271

ENU 142/17



Overview of rear spring strut

Service

142/17 ENU 4271

4



Information

Coil springs must always be replaced in pairs!

3 If you find signs of damage, such as chafing or score marks, **replace** inserts (⇒ *Overview of rear spring strut* -2-), supporting mounts (⇒ *Overview of rear spring strut* -3-), coil springs (⇒ *Overview of rear spring strut* -9-) and shock absorbers (⇒ *Overview of rear spring strut* -12-) on the affected spring strut.



Information

If the insert shows no sign of damage on the outside, it may be damaged by the metal core on the inside.

3.1 Inserts (⇒ Overview of rear spring strut-2-), supporting mounts (⇒ Overview of rear spring strut-3-) and coil springs (⇒ Overview of rear spring strut-9-) must be replaced in pairs. ⇒ Workshop Manual '427137 Disassembling and assembling rear spring strut'




Information

Shock absorbers must always be replaced in pairs when at least one of the following preconditions is met:

- Mileage: 15,500 miles (25,000 km)
- Age: 2 years
- 3.2 Shock absorbers (*⇒ Overview of rear spring strut-12-*) must be replaced in pairs, depending on mileage and age.

End of action required.



Overview of rear spring strut

Technical Information

Service

142/17 ENU 4271

4

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
42713751	Disassembling and assembling rear spring struts	
42713752	Disassembling and assembling rear spring struts	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	42860	Spring-strut mount
Damage type (SA4)	2017	chafing, creaking

References: ⇒ Workshop Manual '427119 Removing and installing rear spring strut'

⇒ Workshop Manual '427137 Disassembling and assembling rear spring strut'

⇒ Workshop Manual '449503 Suspension alignment, complete'

911 Carrera (991)/911 GTS (991)/911 Turbo (991) - with I-no. 478/Central wheel lock:

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
44951550	Adjusting vehicle at front and rear	
44052012	Removing and installing wheels	
44950300	Performing front + rear suspension alignment	
42712050	Removing and installing rear spring struts	
42713850	Disassembling and assembling rear spring struts	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	42860	Spring-strut mount
Damage type (SA4)	2017	chafing, creaking

References: ⇒ Workshop Manual '427119 Removing and installing rear spring strut'

⇒ Workshop Manual '427137 Disassembling and assembling rear spring strut'

⇒ Workshop Manual '449503 Suspension alignment, complete'

Service

4271 ENU 142/17

Technical Information

911 Carrera (991)/911 GTS (991)/911 Turbo (991) - without I-no. 478:

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
44951550	Adjusting vehicle at front and rear	
44052002	Removing and installing wheels	
44950300	Performing front + rear suspension alignment	
42712050	Removing and installing rear spring struts	
42713850	Disassembling and assembling rear spring struts	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	42860	Spring-strut mount
Damage type (SA4)	2017	chafing, creaking

References: ⇒ Workshop Manual '427119 Removing and installing rear spring strut'

⇒ Workshop Manual '427137 Disassembling and assembling rear spring strut'

⇒ Workshop Manual '449503 Suspension alignment, complete'

911 Cabriolet (991)/911 GTS Cabriolet (991)/911 Turbo Cabriolet (991) - with I-no. 478/Central wheel lock:

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
44951550	Adjusting vehicle at front and rear	
44052012	Removing and installing wheels	
44950300	Performing front + rear suspension alignment	
42712065	Removing and installing rear spring struts	
42713850	Disassembling and assembling rear spring struts	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	42860	Spring-strut mount
Damage type (SA4)	2017	chafing, creaking

References: ⇒ Workshop Manual '427119 Removing and installing rear spring strut'

⇒ Workshop Manual '427137 Disassembling and assembling rear spring strut'

⇒ Workshop Manual '449503 Suspension alignment, complete'

Feb 13, 2018 Page 8 of 10

Service

142/17 ENU 4271

4

911 Cabriolet (991)/911 GTS Cabriolet (991)/911 Turbo Cabriolet (991) - without I-no. 478:

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
44951550	Adjusting vehicle at front and rear	
44052002	Removing and installing wheels	
44950300	Performing front + rear suspension alignment	
42712065	Removing and installing rear spring struts	
42713850	Disassembling and assembling rear spring struts	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	42860	Spring-strut mount
Damage type (SA4)	2017	chafing, creaking

References: ⇒ Workshop Manual '427119 Removing and installing rear spring strut'

 \Rightarrow Workshop Manual '427137 Disassembling and assembling rear spring strut'

⇒ Workshop Manual '449503 Suspension alignment, complete'

911 Targa (991)/911 Targa GTS (991) - with I-no. 478/Central wheel lock:

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
44951550	Adjusting vehicle at front and rear	
42712060	Removing and installing rear spring struts	
44052012	Removing and installing wheels	
44950300	Performing front + rear suspension alignment	
42713850	Disassembling and assembling rear spring struts	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	42860	Spring-strut mount
Damage type (SA4)	2017	chafing, creaking

References: ⇒ Workshop Manual '427119 Removing and installing rear spring strut'

⇒ Workshop Manual '427137 Disassembling and assembling rear spring strut'

⇒ Workshop Manual '449503 Suspension alignment, complete'

Feb 13, 2018 Page 9 of 10

911 Targa (991)/911 Targa GTS (991) - without I-no. 478:

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
44951550	Adjusting vehicle at front and rear	
42712060	Removing and installing rear spring struts	
44052002	Removing and installing wheels	
44950300	Performing front + rear suspension alignment	
42713850	Disassembling and assembling rear spring struts	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	42860	Spring-strut mount
Damage type (SA4)	2017	chafing, creaking

References: ⇒ Workshop Manual '427119 Removing and installing rear spring strut'

⇒ Workshop Manual '427137 Disassembling and assembling rear spring strut'

⇒ Workshop Manual '449503 Suspension alignment, complete'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.