



Technical Service Bulletin

93C7 UPDATE – Software Update for Battery Regulation (NVLW)

February 15, 2018

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3 e-Tron	2016	See ELSA	See ELSA

Condition

This Update has been proactively released to prevent the following condition from occurring in the vehicle:

The warning concept for the high-voltage battery has been modified for Audi A3 e-tron vehicles manufactured within a specific period. The “Drive system: system fault!” warning indicator will light up red instead of yellow if moisture is detected inside the high voltage battery.

This Update is in effect until removed.

Vehicle must meet all of the following criteria:

- Procedure is valid only for vehicles that show the **93C7** code in the Elsa Campaign/Action Information screen on the day of repair.
- Vehicle must be within the New Vehicle Limited Warranty.
- Procedure must be performed within the allotted time frame stated in this Technical Service Bulletin.
- Procedure must be performed on applicable vehicles in dealer inventory prior to sale.

Technical Background

The warning concept for the high-voltage battery has been modified for Audi A3 e-tron vehicles manufactured within a specific period. The “Drive system: system fault!” warning indicator will light up red instead of yellow if moisture is detected inside the high voltage battery.

Service

SVM Update Instructions

1. Follow all instructions in TSB 2011732: 00 Software Version Management (SVM), operating instructions.
2. Attach an appropriate battery charger to the vehicle.
3. Switch on the hazard warning lights.

CAUTION

The procedure may cancel itself if the hazard warning lights are not switched on. The hazard warning lights prevent the system from switching to bus sleep mode during the update.

4. Attach the scan tool to the vehicle using an USB cable.
5. Confirm that the scan tool is communicating with the diagnostic head by USB <Green Arrow>. If the Bluetooth symbol is shown <Red Arrow> then disconnect the diagnostic head from the vehicle and then reattach the USB cable to the diagnostic head and then reattach to the vehicle.



6. Using Flashing, perform the update using the SVM action code, **93C7A567**.

NOTE

This SVM code will update all required control modules automatically. The flashing process only has to be performed once.

7. After the Flashing test plan has completed upload log online.

Technical Service Bulletin



Warranty

Claim Entry Instructions

After campaign has been completed, enter claim as soon as possible to help prevent work from being duplicated elsewhere. Attach the Elsa screen print showing action open on the day of repair to the repair order.

If customer refused campaign work or vehicle is out of the specified warranty parameter for this Update:

- ✓ U.S. dealers: Submit the request through Audi Warranty Online under the Campaigns/Update option.
- ✓ Canada dealers: Fax repair order to Warranty at (905) 428-4811.

Service Number	93C7
Damage Code	0099
Parts Vendor Code	002
Claim Type	Sold vehicle: 7 10 Unsold vehicle: 7 90
Causal Indicator	Mark Labor as causal part
Vehicle Wash/Loaner	Do not claim wash/loaner under this action
Criteria I.D.	8V
	Connect battery charger. Labor operation: 2706 8950 10 T.U. --AND-- Connect vehicle diagnostic tester, perform software update for Battery Regulation control unit. Labor operation: 9325 25 99 Time state on diagnostic protocol (max 40T.U.)



Technical Service Bulletin

Additional Actions Some of the affected vehicles may be involved in additional Actions. Please check your Elsa Campaign/Action Information screen so that any *additional required work can be done simultaneously*.

Verifying Vehicle Eligibility To verify vehicle eligibility for this Update, *always* check the Elsa Campaign/Action Information screen. The Elsa system is the *only* binding inquiry and verification system; other systems are not valid and *may result in non-payment* of a claim.

Help for Claim Entry For questions regarding claim entry, contact Audi Warranty.

Required Customer Notification Inform your customer in writing by recording on the Repair Order any and all work that was conducted on the vehicle, including any and all updates completed under this Update.

Additional Information

All parts and service references provided in this Update are subject to change and/or removal. Always check Elsa for the most current version of this document.