# Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject: DRIVER AND/OR PASSENGER SEAT WARMER(S) INOPERATIVE - (CLOTH SEATS ONLY)	Bulletin No.: 09-017/18
	Last Issued: 03/26/2018

## **BULLETIN NOTES**

Previous TSBs:	Date(s) Issued:	
09-016/17	04/27/17 and 06/28/17	


**NOTE:** For vehicles equipped with leather seats, go to TSB 09-015/17.

### **APPLICABLE MODEL(S)/VINS**

2013-2016 CX-5 vehicles equipped with cloth seats.

## DESCRIPTION

Some vehicles may exhibit inoperative driver and/or front passenger side seat warmer(s) in any mode (High, Mid and Low). This may be caused by repeated load applied to the seat cushion (1) while the seat is occupied. A section of the heater mat (2) just above the reinforcement rod (3) in the cushion pad contacts internal heater mat wire and causes damage (4).



Customers having this concern should have their vehicle repaired using the following repair procedure.

#### Page 1 of 4

## **REPAIR PROCEDURE**

1. Verify the customer concern.

2. Replace the seat cushion pad(s) according to the instructions on MGSS online FRONT SEAT CUSHION TRIM REMOVAL/INSTALLATION.

**NOTE**: A new seat cushion pad is available with a repositioned internal heater mat wire to prevent contact with the reinforcement rod.

3. Verify the repair.

## PARTS INFORMATION

Part Number	Description	Qty.	Notes
KEY0-88-11X	Heater and Pad (R), Cushion	1	STC-Cloth B - (2013-2015 CX-5)
KDY9-88-16X	Heater and Pad (L), Cushion	1	STC-Cloth B - (2013-2015 CX-5)
KAYK-88-16X	Heater and Pad (L), Cushion	1	STC-Cloth D - (2016 CX-5)
KF61-88-1H5 02	Recliner Knob (L)	1	Non-reusable part (Before Nov. 1, 2016 vehicle production)
TK48-88-1H5 02	Recliner Knob (L)	1	Non-reusable part (After Nov. 1, 2016 vehicle production)
KD45-88-1G5 02	Recliner Knob (R)	1	Non-reusable part (Before Nov. 1, 2016 vehicle production)
TK48-88-1G5 02	Recliner Knob (R)	1	Non-reusable part (After Nov. 1, 2016 vehicle production)
KD45-88-857 02	Lifter Knob (L)	1	Non-reusable part
KE08-88-807 02	Lifter Knob (R)	1	Non-reusable part
KD45-88-585	Clip	2 or 4	Non-reusable part

#### NOTE:

- Use GEPC with VIN to look up the latest part number(s).
- For vehicles equipped with leather seats, go to TSB 09-015/17.

Page 2 of 4

Heater and Pad, Cushion	
Recliner Knob	
Lifter Knob	R
Clip	

Page 3 of 4

## WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	61
Damage Code	9R
Part Number Main Cause	KEY0-88-11X, KDY9-88-16X or KAYK-88-16X (Enter part number of Heater Pad and Cushion applicable to the subject vehicle)
Quantity	1
Operation Number / Labor Hours:	XXMC7ARX / 0.9 Hrs. (Driver side) XXMC7BRX / 1.1 Hrs. (Passenger side) XXMC7CRX / 1.8 Hrs. (Both sides)

NOTE: This bulletin only applies to vehicle with cloth seats.

Page 4 of 4