Models Discovery / L462 Discovery / L462 Discovery / Sport / L550 Range Rover Evoque / L538 Range Rover Evoque / L538 Range Rover Sport / L494 Range Rover Sport / L494 Range Rover Velar / L560		
Discovery Sport / L550 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494 Range Rover Sport / L494 Range Rover Velar / L560 Title Loss of voice related features after updating InControl Touch Pro with version 17C4 Category Electrical Last modified 23-Mar-2018 00:00:00 Symptom 207000 Entertainment Systems Content Issue: In some cases vehicles that have been updated to InControl Touch Pro version 17C4, the infotainment system can no longer process voice inputs or outputs. Common symptoms are reported as: • Voice commands are not recognized • Voice output such as spoken navigation guidance is inoperative. Cause: During the process of updating the Infotainment Master Control module (IMC) a voice database can become corrupted. While the root cause of this issue is still under investigation, an interim solution is available to replace the corrupted database. Correction: 1. Confirm the symptoms match both descriptions above. 2. If both voice input and output are affected, you will also probably find that the Voice Recognition menu is blank confirming a corrupted database. 1. Open a TA case for escalation to the NGI recovery team. 2. Additional details for scheduling a WebEx session will be provided via the TA process. 3. If the issue is limited to a "voice input only" failure mode, this might be caused by a hardware failure of voice command button or microphone etc. Continue troubleshooting as normal and open a TA if required. NOTE Evoque convertible models do not support voice commands and the "voice command" button on the steering wheel only provides a "mute" function.	Reference	SSM73792
Last modified 23-Mar-2018 00:00:00 Symptom 207000 Entertainment Systems Content Issue: In some cases vehicles that have been updated to InControl Touch Pro version 17C4, the infotainment system can no longer process voice inputs or outputs. Common symptoms are reported as: • Voice commands are not recognized • Voice output such as spoken navigation guidance is inoperative. Cause: During the process of updating the Infotainment Master Control module (IMC) a voice database can become corrupted. While the root cause of this issue is still under investigation, an interim solution is available to replace the corrupted database. Correction: 1. Confirm the symptoms match both descriptions above. 2. If both voice input and output are affected, you will also probably find that the Voice Recognition menu is blank confirming a corrupted database. 1. Open a TA case for escalation to the NGI recovery team. 2. Additional details for scheduling a WebEx session will be provided via the TA process. 3. If the issue is limited to a "voice input only" failure mode, this might be caused by a hardware failure of voice command button or microphone etc. Continue troubleshooting as normal and open a TA if required. NOTE Evoque convertible models do not support voice commands and the "voice command" button on the steering wheel only provides a "mute" function.	Models	Discovery Sport / L550 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494
Symptom 207000 Entertainment Systems Content Issue: In some cases vehicles that have been updated to InControl Touch Pro version 17C4, the infotainment system can no longer process voice inputs or outputs. Common symptoms are reported as: • Voice commands are not recognized • Voice output such as spoken navigation guidance is inoperative. Cause: During the process of updating the Infotainment Master Control module (IMC) a voice database can become corrupted. While the root cause of this issue is still under investigation, an interim solution is available to replace the corrupted database. Correction: 1. Confirm the symptoms match both descriptions above. 2. If both voice input and output are affected, you will also probably find that the Voice Recognition menu is blank confirming a corrupted database. 1. Open a TA case for escalation to the NGI recovery team. 2. Additional details for scheduling a WebEx session will be provided via the TA process. 3. If the issue is limited to a "voice input only" failure mode, this might be caused by a hardware failure of voice command button or microphone etc. Continue troubleshooting as normal and open a TA if required. NOTE Evoque convertible models do not support voice commands and the "voice command" button on the steering wheel only provides a "mute" function.	Title	·
Content Issue: In some cases vehicles that have been updated to InControl Touch Pro version 17C4, the infotainment system can no longer process voice inputs or outputs. Common symptoms are reported as: • Voice commands are not recognized • Voice output such as spoken navigation guidance is inoperative. Cause: During the process of updating the Infotainment Master Control module (IMC) a voice database can become corrupted. While the root cause of this issue is still under investigation, an interim solution is available to replace the corrupted database. Correction: 1. Confirm the symptoms match both descriptions above. 2. If both voice input and output are affected, you will also probably find that the Voice Recognition menu is blank confirming a corrupted database. 1. Open a TA case for escalation to the NGI recovery team. 2. Additional details for scheduling a WebEx session will be provided via the TA process. 3. If the issue is limited to a "voice input only" failure mode, this might be caused by a hardware failure of voice command button or microphone etc. Continue troubleshooting as normal and open a TA if required. NOTE Evoque convertible models do not support voice commands and the "voice command" button on the steering wheel only provides a "mute" function.	Category	Electrical
Content Issue: In some cases vehicles that have been updated to InControl Touch Pro version 17C4, the infotainment system can no longer process voice inputs or outputs. Common symptoms are reported as: • Voice commands are not recognized • Voice output such as spoken navigation guidance is inoperative. Cause: During the process of updating the Infotainment Master Control module (IMC) a voice database can become corrupted. While the root cause of this issue is still under investigation, an interim solution is available to replace the corrupted database. Correction: 1. Confirm the symptoms match both descriptions above. 2. If both voice input and output are affected, you will also probably find that the Voice Recognition menu is blank confirming a corrupted database. 1. Open a TA case for escalation to the NGI recovery team. 2. Additional details for scheduling a WebEx session will be provided via the TA process. 3. If the issue is limited to a "voice input only" failure mode, this might be caused by a hardware failure of voice command button or microphone etc. Continue troubleshooting as normal and open a TA if required. NOTE Evoque convertible models do not support voice commands and the "voice command" button on the steering wheel only provides a "mute" function.	Last modified	23-Mar-2018 00:00:00
Touch Pro version 17C4, the infotainment system can no longer process voice inputs or outputs. Common symptoms are reported as: • Voice commands are not recognized • Voice output such as spoken navigation guidance is inoperative. Cause: During the process of updating the Infotainment Master Control module (IMC) a voice database can become corrupted. While the root cause of this issue is still under investigation, an interim solution is available to replace the corrupted database. Correction: 1. Confirm the symptoms match both descriptions above. 2. If both voice input and output are affected, you will also probably find that the Voice Recognition menu is blank confirming a corrupted database. 1. Open a TA case for escalation to the NGI recovery team. 2. Additional details for scheduling a WebEx session will be provided via the TA process. 3. If the issue is limited to a "voice input only" failure mode, this might be caused by a hardware failure of voice command button or microphone etc. Continue troubleshooting as normal and open a TA if required. NOTE Evoque convertible models do not support voice commands and the "voice command" button on the steering wheel only provides a "mute" function.	Symptom	207000 Entertainment Systems
For this vehicle this issue only applies to voice output such as	Content	Touch Pro version 17C4, the infotainment system can no longer process voice inputs or outputs. Common symptoms are reported as: • Voice commands are not recognized • Voice output such as spoken navigation guidance is inoperative. Cause: During the process of updating the Infotainment Master Control module (IMC) a voice database can become corrupted. While the root cause of this issue is still under investigation, an interim solution is available to replace the corrupted database. Correction: 1. Confirm the symptoms match both descriptions above. 2. If both voice input and output are affected, you will also probably find that the Voice Recognition menu is blank confirming a corrupted database. 1. Open a TA case for escalation to the NGI recovery team. 2. Additional details for scheduling a WebEx session will be provided via the TA process. 3. If the issue is limited to a "voice input only" failure mode, this might be caused by a hardware failure of voice command button or microphone etc. Continue troubleshooting as normal and open a TA if required. NOTE Evoque convertible models do not support voice commands and the "voice command" button on the steering wheel only provides a "mute" function.
		"mute" function.

navigation guidance

ŀ

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

- 1 = Poor Basic information provided The SSM does not help me resolve the customer concern.
- 3 = Average Adequate information provided The SSM partially helps me resolve the customer concern.
- 5 = Excellent All required information provided to resolve the customer concern.