Mazda North American Operations Irvine, CA 92618-2922



Subject: MULTIPLE WARNING LIGHTS ON DUE TO LOOSE G05 GROUND CONNECTION	Service Alert No.: SA-006/18
	Last Issued: 02/14/2018

APPLICABLE MODEL(S)/VINS

2017 CX-5

DESCRIPTION


Some customer may complain about multiple warning lights illuminated. Additional symptoms may include:

- Engine will not turn OFF
- Power Liftgate will not open
- DSM HU/CM network test failure
- Any of the following DTC's stored:

DTC	Description
U2005:86	Error signal received from PCM
U0121:00	Communication error with DSC HU/CM
U0401:00	CAN system communication error
U2005:68	Error vehicle speed signal received from PCM
U3003:16	Power supply system
U0100:00	Communication error with PCM
C1105:62	Brake light signal malfunction
C1A67:92	Radar unit sensitivity lowered
U0301:09	Error signal received from PCM
U0316:09	Error signal received from DSC HU/CM
U0121:87	Communication error with DSC HU/CM

Page 1 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing. This may be caused by a loose G05 ground connection.




REPAIR PROCEDURE

1. Check G05 bolt torque. If loose, torque to specification.

Bolt torque specification 80-106 in lbf (9-12 Nm, 92-122 kgf cm)

Note: If G05 bolt torque is OK, wiggle eye terminal. If loose, replace bolt and torque to specification.



2. Verify repair

Page 2 of 2

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.