

SI B34 05 15 Brakes February 2018 Technical Service

TICKING NOISE FROM THE FRONT AXLE WHEN CORNERING

New information provided by this revision is preceded by this symbol

This Service Information bulletin replaces SI B34 05 15 dated April 2017

What's New:

- Correction updated
- · Procedure: Video clip to verify noise and further troubleshooting

MODEL

F06 (M6 Gran Coupe)	F10 (M5)	F12 (M6 Convertible)	F13 (M6)
F80 (M3)	F82 (M4)	F83 (M4 Convertible)	F85 (X5M)
F86 (X6M)			
All from start of production			

SITUATION

The customer may complain of a metallic ticking noise from the front axle when cornering, maneuvering, parking or pulling away from a parking space.

CAUSE

Movement between the inner contact surfaces of the brake disc and drive flange of the wheel bearing hub.

After verifying the noise, clean the contact surfaces and install friction washer.

PROCEDURE

(https://tinyurl.com/V340515).

- Remove both front wheels and rotate them on their hub one wheel bolt hole (wheel rotates, hub/rotor stays stationary) and torque the wheels.
- · Test drive the vehicle again.

• If the noise still persists: the cause can be from premature wear on the constant velocity joints on the outer (wheel side) ends of the front output shafts. Refer to SI B31 01 17 for further diagnosis/repairs.

• If the noise is no longer present: perform the attached front wheel cleaning and friction ring installation procedure

PARTS INFORMATION

https://www.bmwtis.net/tiscode/cgi-bin/bulletin.aspx?sie_path=/tsb/bulletins/htm_store/454... 3/5/2018

Part Number	Description	Quantity
31 10 8 053 073	Disc for higher coefficient of friction	4

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	3121900100	
Labor Operation:	Labor Allowance:	Description:
00 64 301	Refer to KSD2	Rework the (front) brake discs and wheel contact surfaces (including installing the friction discs) (Main work)
Or:		
00 64 866	Refer to KSD2	Rework the (front) brake discs and wheel contact surfaces (including installing the friction discs) (Plus work – Vehicle is already in the workshop)
Or:		
00 64 867	Refer to KSD2	Rework the (front) brake discs and wheel contact surfaces (including installing the friction discs) (wheels removed) (Associated work)

Overlapping Labor Procedure – Other Repairs

If invoicing the KSD2 flat rate labor operation codes for other repair work results in overlapping labor, for those flat rate labor operations that are affected, you can now:

• Replace the stated KSD2 "FRU allowance" with a "reduced FRU value" to eliminate the overlapping labor.

For help in identifying the overlapping labor, please refer to the AIR FRU Plausibility Check (Overlapping Labor Tool) that is located in the AIR Client.

Eligible other repair work being claimed under a different defect code will require separate punch times.

On the repair order and in the claim comment section, please identify and itemize those labor operations being claimed with a "reduced FRU value."

Posted: Tuesday, February 27, 2018

ATTACHMENTS

View PDF attachment **B340515** Attachment A.

[Copyright ©2018 BMW of North America, Inc.]

Front Wheel Cleaning and Friction Ring Installation Procedure



Attachment A	February 2017	(SI B34 05 15)
	GRUSB3417-01	8. Clean the rims on the inside on the bearing surface to the brake disk with a sand paper (80-grit) in the radial direction.
	GRUSB3417-02	 Install guide pins into wheel hub to hold friction ring in place.
	GRUSB3417-03	Note: de pins can be made by removing head of a wheel bolt and then ting it (A); or sourced locally from vendors (B).

Attachment A



 Reinstall wheel, after the installation of the first three wheel bolts (C) the guide pins (D) can be removed and the last two wheel bolts inserted.