



Service Bulletin

File in Section: -

Bulletin No.: 18-NA-070

Date: March, 2018

TECHNICAL

Subject: Service Side Detection Message Displayed in Driver Information Center (DIC), DTC U0155 Set

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2018	2018	SOP	February 08, 2018		
Holden	Equinox	2018	2018				

Involved Region or Country	North America, N.A. Export Regions, Australia
Additional Options (RPOs)	Vehicles equipped with SIDE ACTIVE SAFETY-OBSTACLE DETECTION ENHANCED (RPO UKC)
Condition	Some customers may comment on the service side detection message being displayed in the driver information center (DIC). Some technicians may find DTC U0155 (Lost Communication With Instrument Cluster) set in the Side Object Sensor Module.
Cause	This condition may be caused by a software anomaly.
Correction	An updated software calibration has been released to address this condition.

Service Procedure

Refer to *B218L Side Object Sensor Module - Left: Programming and Setup* in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810765	Side Object Sensor Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	Released March 05, 2018

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION