

## **Service Bulletin**

File in Section:

Bulletin No.: 18-NA-076

Date: March, 2018

# **TECHNICAL**

Subject: No CD Audio Present Following Replacement of the Video Player Assembly

| Brand:    | Model:    | Model Year: |      | VIN: |    | Engino  | Transmission: |
|-----------|-----------|-------------|------|------|----|---------|---------------|
|           |           | from        | to   | from | to | Engine: |               |
| Cadillac  | Escalade  | 2015        | 2015 |      |    | All     | All           |
| Chevrolet | Silverado | 2015        | 2015 |      |    | All     | All           |
| GMC       | Sierra    | 2015        | 2015 |      |    | All     | All           |

| Involved Region or Country | North America and NA Export vehicles   |
|----------------------------|--|
| Additional Options (RPOs)  | Equipped with Rear Seat Entertainment (RPO U42 or UWG) And Previously Serviced with Replacement Video Player Part Number 84214291                  |
| Condition                  | Some customers may comment on no CD audio following replacement of the video player assembly.  |
| Cause                      | This may be the result of a software concern with replacement video player assemblies (PN 84214291) that were manufactured on 8/6/2017 or earlier. |
| Correction                 | Refer to the procedure below for the proper correction.  |

#### **Service Procedure**



If this concern is encountered, remove the video player assembly and inspect the date code shown above.

If the unit was manufactured 8/6/2017 or earlier, replace the video player assembly again and ensure the replacement was manufactured 8/7/2017 or later before installing it. Refer to *Video Player Assembly Replacement* in Service Information for detailed replacement instructions.

#### **Parts Information**

| Causal<br>Part | Description          | Part<br>Number | Qty |
|----------------|----------------------|----------------|-----|
| Х              | PLAYER ASM-<br>VIDEO | 84214291       | 1   |

4999542

Page 2 March, 2018 Bulletin No.: 18-NA-076

### **Warranty Information**

For vehicles repaired under warranty use:

| Labor Operation | Description                   | Labor Time                            |
|-----------------|-------------------------------|---------------------------------------|
| 3423150         | Video Disc Player Replacement | Use Published Labor<br>Operation Time |

| Version  | 1                       |
|----------|-------------------------|
| Modified | Released March 08, 2018 |