

Service Bulletin

WARRANTY ADMINISTRATION

- Subject: GM of Canada New Vehicle Tire Warranty Program and GWM Transaction Submission Information
- Models: 2019 and Prior GM Passenger Cars and Light Duty Trucks

Attention: This Service Bulletin is Applicable to "GM of Canada Dealers" Only.

This Bulletin has been revised to add Model Year 2019 vehicles, update the Inspection Station Locations for Tire Returns shipping address for tires being sent to Bridgestone and add information under What is Not Covered by the New Vehicle Tire Warranty Program. Please discard Corporate Bulletin Number 01-03-10-003P.

GM of Canada New Vehicle Tire Warranty Program

The new tires that the vehicle are equipped with are covered by General Motors against defects in material or workmanship under the New Vehicle Warranty (Base Warranty Coverage). For vehicles within this warranty period, defective tires will be replaced on a pro rata adjustment basis according to the following distance-based schedule:

- Buick and Cadillac up to 80,000 km
- Chevrolet and GMC up to 60,000 km

Notice: If the tire is not in stock and the vehicle is returned to the Customer while the tire is being shipped, the vehicle distance at the time the tires were ordered must be recorded on the Job Card and used to determine the proration amount. Any additional accrued vehicle odometer reading between ordering and installation of the tires should not be charged to the Customer.

- The Customer contributes to the cost of the tire replacement based on vehicle odometer reading. A proration system is used, with Customer Participation increasing incrementally as the vehicle odometer reading increases.
- See the applicable GM Tire Warranty Proration Table in this Bulletin for further Cost and Participation details.
- The proration is based solely on vehicle odometer reading. Tread depth measurements and/or seasonal tire usage are not pertinent for the purposes of this calculation and are *not required* for GWM Transaction submissions.

Notice:

- Proration applies to the price of the "tires" only. Cost plus warranty mark-up must be calculated before determining the prorated amount. No labour charges are to be assessed to the Customer for tire replacement. GM will cover 100% of the cost for labour (mount and balance tires) for tires replaced under the Base Warranty Coverage, based on published allowances in the Labour Time Guide.
- Tire proration policies and percentages also apply to tires replaced under Customer Enthusiasm.

2017–2019 Buick and Cadillac Tire Warranty Proration Table

waitanty i foration fable					
Vehicle Odometer Reading in Kilometres (km)	Customer Participation Tire Cost Including Markup	Customer Participation Labour = Mount and Balance			
0-19,000	0%	0%			
19,001 - 24,000	40%	0%			
24,001 - 32,000	50%	0%			
32,001 - 40,000	60%	0%			
40,001 - 48,000	70%	0%			
48,001 - 80,000	80%	0%			
80,001+	100%	100%			

2017–2019 Buick and Cadillac Tire Warranty Proration Table

2017–2019 Chevrolet and GMC Tire Warranty Proration Table

2017–2019 Chevrolet and GMC Tire Warranty Proration Table

Vehicle Odometer Reading in Kilometres (km)	Customer Participation Tire Cost Including Markup	Customer Participation Labour = Mount and Balance
0-19,000	0%	0%
19,001 - 24,000	40%	0%
24,001 - 32,000	50%	0%
32,001 - 40,000	60%	0%
40,001 - 48,000	70%	0%
48,001 - 60,000*	80%	0%
60,001+*	100%	100%

*The 2017 Canadian Limited Warranty and Owner Assistance Information booklet may have this tire prorated scale shown as up to 57,600 km instead of 60,000 km. The tire warranty prorated scale for Chevrolet/GMC vehicles is up to 60,000 km and will be corrected in future editions of the booklet.

2016 and Prior GM Tire Warranty Proration Table

2016 and Prior GM Tire Warranty Proration Table

Vehicle Odometer Reading in Kilometres (km)	Customer Participation Tire Cost Including Markup	Customer Participation Labour = Mount and Balance		
0-20,000	0%	0%		
20,001 - 20,999	33%	0%		
21,000 - 21,999	34.2%	0%		
22,000 - 22,999	35.3%	0%		
23,000 - 23,999	36.5%	0%		
24,000 - 24,999	37.7%	0%		
25,000 - 25,999	38.9%	0%		
26,000 - 26,999	40.0%	0%		
27,000 - 27,999	41.2%	0%		
28,000 - 28,999	42.6%	0%		
29,000 - 29,999	43.6%	0%		
30,000 - 30,999	44.7%	0%		
31,000 - 31,999	45.9%	0%		
32,000 - 32,999	47.1%	0%		
33,000 - 33,999	48.3%	0%		
34,000 - 34,999	49.4%	0%		

2016 and Prior GM Tire Warranty Proration Table (cont'd)

		/
Vehicle Odometer Reading in Kilometres (km)	Customer Participation Tire Cost Including Markup	Customer Participation Labour = Mount and Balance
35,000 - 35,999	50.6%	0%
36,000 - 36,999	51.8%	0%
37,000 - 37,999	53.0%	0%
38,000 - 38,999	54.1%	0%
39,000 - 39,999	55.3%	0%
40,000 - 40,999	56.5%	0%
41,000 - 41,999	57.7%	0%
42,000 - 42,999	58.8%	0%
43,000 - 43,999	60.0%	0%
44,000 - 44,999	61.2%	0%
45,000 - 45,999	62.4%	0%
46,000 - 46,999	63.5%	0%
47,000 - 47,999	64.7%	0%
48,000 - 48,999	65.9%	0%
49,000 - 49,999	67.1%	0%
50,000 - 50,999	68.2%	0%
51,000 - 51,999	69.4%	0%
52,000 - 52,999	70.6%	0%
53,000 - 53,999	71.8%	0%
54,000 - 54,999	72.9%	0%
55,000 - 55,999	74.1%	0%
56,000 - 56,999	75.3%	0%
57,000 - 57,999	76.5%	0%
58,000 - 58,999	77.6%	0%
59,000 - 60,000	78.8%	0%
60001+ (Chevrolet, GMC)	100.0%	100%
60,001 - 80,000 (Buick/ Cadillac Only)	80.0%	0%
80,001+ (Buick/ Cadillac Only)	100.0%	100%

Using the applicable GM Tire Warranty Proration Tables, the Service Personnel should be able to calculate the required Customer Participation (contribution) for each scenario. Here are a few examples:

- A 2017 Buick with 23,139 km requires *both front tires* to be replaced. The full cost of each tire including handling allowance is \$172.72. In this example, the customer participation is 40.0% of the tire replacement cost calculated as follows: \$172.72 x 2 tires = \$345.44 x 40.0% = \$138.18. GM will cover the remaining portion for the tires (\$345.44 \$138.18 = \$207.26) and 100% of the labour to mount and balance the new tires.
- A 2016 Chevrolet with 30,435 km requires one tire be replaced. The full cost of the tire including handling allowance is \$156.20. In this example, the Customer participation is 44.7% of the tire replacement cost calculated as follows: \$156.20 x 44.7% = \$69.82. GM will cover the remaining portion for the tire (\$156.20 \$69.82 = \$86.38) and 100% of the labour to mount and balance the new tire.
- A 2017 Cadillac with 67,593 km requires one rear tire to be replaced. The full cost of the tire including handling allowance is \$215.46. In this example, the Customer participation is 80% of the tire replacement cost calculated as follows:
 \$215.46 x 80% = \$172.37. GM will cover the remaining portion for the tire (\$215.46 -\$172.37 = \$43.09) and 100% of the labour to mount and balance the new tire.

What Is Covered by the New Vehicle Tire Warranty Program

- Original Equipment (OE) tires and PDI installed Limited Production Option (LPO) tires are covered. Most OE and LPO tires will have a Tire Performance Criteria (TPC) number molded on the sidewall near the tire size.
- Tires replaced under warranty will continue to be covered for the remaining portion of the Base Warranty Coverage. Proration should be based off of the accumulated distance on the replacement tire, using the GM Tire Warranty Proration Table, through the end of the vehicle's New Vehicle Base Warranty Coverage term.

Use of GM Tire Sealant

General Motors may recommend/endorse practices that differ from those of individual tire manufacturers. One example is that the temporary use of tire sealant (as supplied with a GM inflator kit) may not be endorsed by certain tire manufacturers, such as Pirelli or Bridgestone. General Motors has independently validated the temporary use of such sealant when used in accordance with the instructions provided in the vehicle Owner Manual.

When the instructions found in the Owner Manual have been followed correctly, GM of Canada will continue to cover the tire under the terms of the New Vehicle Warranty, whether or not the practice conflicts with the policies of the individual tire manufacturer. Due to this policy, it may be advantageous for a customer with Bridgestone or Pirelli tires to return their vehicle to a General Motors Dealership for tire warranty issues if GM Tire Sealant has been used.

GM Inflator Kits — Tire Pressure Monitor Sensors

ONLY use the tire sealant included with GM Inflator Kits for temporary repair of tire air leaks. General Motors has tested this sealant and its compatibility with on-wheel mounted tire pressure monitor sensors. After inflator kit use, the on-wheel mounted tire pressure sensor should be inspected for any damage, and replaced and/or cleaned as needed.

Tire Chunking on New Vehicles



4251003

This condition may be seen on new vehicles at the time of delivery to the Dealer. The condition, known as *tire chunking* is not transportation damage, but damage from Dynamic Vehicle Testing (DVT) that was performed at the assembly plant. This type of damage is to be treated as a *Warranty Repair*, using the applicable tire labour operation listed in this Bulletin and following the Tire Pre-Repair Authorization process. Because this condition is normally discovered when the Pre-Delivery Inspection (PDI) is performed, *do not* use the GM Tire Warranty Proration Table.

What Is Not Covered by the New Vehicle Tire Warranty Program

- Michelin Pilot Sport CUP tires.
- Non-Original Equipment tires (excluding Dealer replaced tires under the New Vehicle Warranty).

Important: Tire wear greatly varies by both the tire type installed and the driving habits of the owner. OEM tires installed on GM vehicles are evaluated for many different criteria and may have been selected to optimize handling, ride quality, load carrying and/or traction demands. Different types of tires will experience different rates of wear, resulting from these factors. No warranty is offered on the usable tread life of the tires.

- Normal tire wear.
- Tires on a vehicle after the Base Warranty Coverage expires. Original Equipment tires may still have prorated warranty coverage by the tire manufacturer once the Base Warranty Coverage expires.
- Tires purchased by consumers for use as winter tires, beyond the New Vehicle Warranty Program or replaced during the New Vehicle Warranty period for non-warrantable conditions.

Important: If tire replacement is necessary due to component(s) covered under the New Vehicle Warranty, Service Agents may claim for replacement tires on the same Job Card as the defective component(s). The tire claim must be submitted using the applicable tire labour operation and proration schedule listed in this bulletin. A Tire Pre-Repair Authorization is required for the tire labour operation.

 Uneven wear from damaged, worn or misaligned suspension components.

Important: Road hazard may be covered by certain Tire Manufacturers on specific tires.

- Road hazard is not covered. This includes punctures, cuts, impact breaks, etc. Refer to the section titled: Examples of Non-Warrantable Conditions in this Bulletin.
- Damage resulting from driving with low tire pressures.
- Damage resulting from improper tire repairs.
- Damage resulting from extended driving on a flat tire (Except Run-Flat and Self-Sealing Tires).
- Damage due to misuse, negligence, lack of maintenance, alteration, racing and vandalism is not covered.
- Flat spotting caused by parking a vehicle for an extended period of time. See Article 2.1.2 of the Transportation, Vehicle Storage and PDI Policy Manual for tire care policies while vehicles are in dealer inventory.
- Premature and/or excessive wear on Michelin Pilot Sport CUP/CUP2 and Goodyear Eagle F1 Supercar 3R tires.
- Cold weather cracking on high performance summer tires. See Bulletin 13-03-10-001 for further details.
- Some tire weathering and superficial cracking is normal. Tires must not be replaced under the New Vehicle Limited Warranty for this condition.

Examples of Non-Warrantable Tire Conditions

Important: The following examples are only a sampling of non-warrantable conditions submitted in warranty tire returns. GM of Canada is not responsible for, and WILL NOT replace tires sent in for conditions under the "What is Not Covered" section in this Bulletin. Tires replaced under the Tire Warranty Program for non-warrantable conditions are subject to charge back. Inspection of tires replaced under warranty reveals that the most frequent non-warrantable condition claimed is road hazard, followed by improper wear. The following are photos of returned tires that DO NOT have warrantable conditions and a subsequent chargeback (debit) was processed after inspection.



1967355

• This tire has two non-warrantable conditions. The tire is badly worn on the inside shoulder (over extended mileage) and has suffered air leakage from a screw still in the tread.



1967358

• This tire was returned for air leakage. The source of the air leakage is a tire repair plug installed in a non-approved portion of the tire. This tire has road hazard damage.




1967361

• This tire shows sidewall damage extending completely around the tire. This damage is the result of extended driving on a tire that is completely flat. The extensive sidewall wear is from tire contact with the road while it rotates.



1967352

 This tire was damaged by extended driving with little or no air, same as the tire previously shown. This photo shows the inside view. Shredding of the inside may not always be accompanied by obvious exterior damage.



2034306

• This example of common road damage is called a *rim-pinch*. The damage to the tire is caused by the tire folding and contacting the rim and the pavement. Frequently this type of damage will cause a sidewall bulge/bubble when the tire is re-inflated, due to the air attempting to leak from the internal sidewall breakage. It is common for the rim-pinch damage to be visible only from the inside of the tire. A typical tear to the sidewall from this type of damage is shown.

Example of Normal Wear and Age Related Conditions



Some tire weathering and superficial cracking is normal. Tires should not be replaced under the New Vehicle Warranty for this condition.

Page 6

Tire Rotation and Care

Please advise customers of the importance of regular tire rotations and maintaining the specified air pressure for their tires. The vehicle Owner Manual contains tire rotation requirements. Placards located in the door jamb, glove box or under the trunk lids of GM vehicles state the recommended tire pressures for the vehicle.

Processing Tire Warranty Transactions Using Global Warranty Management

Once a customer agrees to tire replacement and their responsible portion under the GM Tire Warranty Program, follow these steps to complete the Transaction:

STEP ONE: Complete a Pre-Repair Authorization (PRA)

Complete a Pre-Repair Authorization (PRA) A PRA must be generated for all tire Warranty Transactions. To access New Pre-Repair

Authorizations, go to the main GWM sitemap, click on Prepare & Submit Transactions and select Search/ Create a Pre-Repair Authorization Document. Click on the NEW button at the bottom of the screen. At the New Pre-Repair Authorization Screen, enter the Business Unit from the dropdown (GM –Canada) then enter the Transaction Type from the dropdown (such as ZREG – Regular Vehicle Transaction) then select the Pre-Repair Type from the dropdown (Tire Replacement). Click on the GO button. A New Pre-Repair Authorization screen will appear, that has both a Pre-Repair Authorization *tab* and a Tire Authorization *tab*.

The prorated amount of the tire only will be submitted as "Customer Participation" on the Transaction submission screen of GWM.

<u>M</u>		Close Window 🕄
lew Pre-Repair Aut	horization	۰ 🗗
his screen allows Global Warra	nty Management Users to create nev	v Pre Repair Authorizations.
Business Unit": GM -	Canada	Z
	Regular Vehicle Transaction	×
Pre-Repair Type": Tre R	eplacement	
		00
re-Repair Tire Aut	horization	
ser Name: Janet Sutherland		"Required Fields
		Disclaimer: All amounts are before taxes
BAC':	VALIDATE	Disclaimer: All amounts are before taxes
BAC':	VALIDATE	Disclaimer: All amounts are before taxes
	VALIDATE	Disclaimer: All amounta are before taxes
Service Agent:	VALIDATE	Disclaimer: All amounts are before taxes
Service Agent:	VALIDATE	Disclaimer: All amounts are before taxes
Service Agent: Contact Name: Phone Number: Fax Number: Contact Email	VALIDATE	Disclaimer: All amounts are before taxes
Service Agent: Contact Name: Phone Number: Fax Number:	VALCATE	Disclaimer: All amounts are before taxes
Service Agent: Contact Name: Phone Number: Fax Number: Contact Email Address:	VALCATE	Disclaimer: All amounts are before taxes
Service Agent: Contact Ilame: Phone Number: Fax Number: Contact Email Address: Job Card?;	VALCATE	Disclaimer: All amounts are before taxes

2440511



Click on the Pre-Repair Authorization tab and fill in the appropriate information as shown in the following list. Those items that are required will have an asterisk shown next to the heading.

- BAC*
- Service Agent
- Contact Name
- Phone Number
- Fax Number
- Contact E-mail Address
- Job Card*
- Job Card Date*
- Reference Number (optional)
- VIN*
- Vehicle Make
- Vehicle Model
- Odometer*
- Transaction Flag
- Customer Complaint Category*
- Complaint Code*
- Description* (for Complaint Code)
- Cause Code*
- Description* (for Cause Code)
- Correction Description*
- Labour Operation*
- Labour Time, including Supplemental Time and/or OLH Time
- Labour Rate
- Labour Total
- Parts Total
- Part Numbers
- Net Item Type and Amount
- Net Item Total
- Tax
- Deductible

Page 7

- Total Before Taxes
- Auth Code
- Comment*

Then click on the Tire Authorization tab and fill in the appropriate information as shown in the following list:

M				iose Window 🛛	Î	
ew Pre-Rep	air Authorization			0		
s screen allows Gk	bal Warranty Management	Users to create new Pre Re	pair Authorizations.			
	t": GM - Canada		×			
	e": ZREO-Regular Vehick	Transaction	×			
Pre-Repair Typ	"I Tire Replacement	_				
			60			
e-Repair thorization	Tire Authorization					
er Name: Janet Sut	herland			*Required Fields		
			sclaimer: All amour	its are before tax	es	
	d": «Make Selection»	*				
	o": Iake Selection> 💌				-	
e Position*:	lake Selection>	Tire Performance Criter	a Number	POPULATE		
	Jake Selection>	(TPC)*: Tire Size*:				
1	/ake Selection> 💌	DOT Code*:		_		
moval d	/ake Selection> 💌					
	cking, bilstering, tread sepa	ration or other structural cor in was caused by a road he	dition that was not ca	used by a road		
Yes ONo	not select in es in conditio	m was caused by a road na	28/0".			
	se damage to any other par	ts of the vehicle?":			-	
Yes C No					24	
					24	-41
M				ia fenitre 🛛	-	
_						
	risation de répara	tion		00		
réalable						
et écran permet aux réalable.	utilisateurs de Gestion garant	ie globale de créer des nouvel	les autorisations de rép	aration		
Unité commercia	e"; Gtil - Canada		×			
	OT: ZREGTransaction de v		×			
Type de réparat préalab	on Remplacement des prieu e*:	a .	×			
		ALI	.ER			
utorisation de						
éparation réalable	Autorisation de pneu					
) de futilisateur; Jan	et Sutherland			Champs requis		
	Clau	se de non-responsabilité: 1	fous les montants s	ont avant taxes		
Marque de pri	cu': «Fates un choix»					
Nom du pri	eu'i «fates un choix» 💌					
PNEU Nº #1						
Position du preu*:	«Fates un choto»	Numéro de critère performance de p	feus"			
Type de flanc*:	«Faites un choix» 💌	Dimensiona des pr	HEMPER	<u> </u>		
Emplacement du	<pates choice<="" td="" un=""><td>Code DOTh:</td><td></td><td>_</td><td></td><td></td></pates>	Code DOTh:		_		
défaut". Raison de la	(Fates un cholo)		I			
suppression*:		es séparations de la sculpture	no but active documents	structured 5	-1	
we presented	vva vladnesi oca codocal o	va avyaracena ee la scupture	va vat estre oormage	1000000 B		40

Those items that are required will have an asterisk shown next to the heading:

- Tire Brand*
- Tire Name*
- Tire Position*
- Sidewall Type*
- Defect Location*
- Removal Reason*
- Tire Performance Criteria Number (TPC)*
- Tire Size*
- DOT Code*

Select a YES/NO radio button to answer the question: Was there visible cracking, blistering, tread separation or other structural condition that was not caused by a road hazard on the tire?* (Do not select "YES" if the condition was caused by a road hazard, or suspension misalignment, or for noise, vibration or tread wear conditions.)

Note: The purpose of this selection is to verify that in the servicing dealers judgement, the tire was replaced due to an inherent structural problem in the tire (not road hazard, customer enthusiasm, etc.).

Select a YES/NO radio button to answer the question: Did the tire issue cause damage to any other parts of the vehicle?*

⇒ If there is more than one defective tire being replaced on the same vehicle, click on the NEXT TIRE SAME VEHICLE button and enter the appropriate information for the next tire.

When completed, click on the SAVE button or SAVE AND ADD ATTACHMENTS button.

STEP TWO: Print the Tire Replacement Document

Print the Tire Replacement Document Print the Tire Replacement Document, attach it to the Job Card and retain with the Vehicle History File. The Tire Replacement Document is generated in GWM at the time the PRA is completed.

Note: STEP TWO will only be necessary if the tires are required to be shipped back; please see STEP THREE below. However, as mentioned in the Service Policies and Procedure (article 3.2.8), the service agent must keep all records relating to transactions for reimbursement for a minimum of twenty-four (24) months after the date of the job card.

	HOMETOW	/N CHEVROLET	
	GWM TIRE REPLA	CEMENT DOCUMENT	
	Tire ID	#:1725522	
	Tin	e#1of1	
original equipment tires will have	ave a Tire Performance Criteria (nation must be completed on this	TPC) number molded on the sid	New Vehicle Tire Warranty. Most ewall. Road hazard and wear-out der to replace the tire and process
Service Agent Name/	Location		
BAC	123456	Service Agent Name	HOMETOWN CHEVROLET
Address	123 MAIN STREET	City	CALGARY
GM Region	1105 WESTERN WM 5	State/Prov	AB T3C 2E4
Country	CA	Postal Code	100 224
Service Agent Contac	t Information		
Contact Name	TIM HORTON	Contact Phone Number	4031234567
Contact Email Address	SMGR@HOMETOWN	Fax Number	
Vehicle Information			
VIN	1GYS4CKJ7GR443322	Model Year	2016
Vehicle Make Description	CADILLAC	Vehicle Model	ESCALADE
Vehicle Mileage	6112	Job Card Number	691028
		MPLE	02/01/2017
Tire Information			
Tire Brand	Bridgesto	Virestane -	DUELER HL ALENZA
Sidewall Type	Blackwall		
Tire Performance Criteria	1427MS		
DOT Code	OBOR	Tire Size	P285/45R22
Replaced Tire Informa	ation		
Tires may be required to be re	eturned to the appropriate Tire M	anufacturer.	
Defect Location	Tire Side Wall	Tire Position	Left Front
Removal Reason	Vibration		
If Removal Reason is Other, give reason for removal			
Is Tire Damaged		No	
Tire Cause Vehicle Damage		No	
Additional Shipping In	formation		
Create Date	02/03/2017	Shipping Label Number	1ZR6A3852020811234
Signature:			

STEP THREE: Returning Replaced Tires (if requested):

Required Tire Return and Shipping Instructions Based on the information entered into GWM, you may be required to return the replaced tire as a condition of the GM New Vehicle Warranty. You will be required to return the tire if either of the following occurs:

- The vehicle has been damaged or the tire displays physical damage.
- The vehicle odometer has less than 20,000 km.



4702643

Fold the GWM Tire Replacement Document at the "Fold Here" line and attach the document to the tire being returned using clear packing tape, with the shipping label shown above facing outwards.

Important: When tires replaced under warranty are shipped back to the tire manufacturer, you must use the UPS shipping label(s) generated by Global Warranty Management (example shown in the image above). You are required to use one (1) UPS shipping label per tire. You are NOT allowed to ship multiple tires with a single UPS shipping label, even if the UPS Agent says it is OK to do so. If you ship multiple tires with a single UPS label, the Tire Pre-Repair Authorization (PRA) will remain in "New" status and will NOT move to "Accept" status. Consequently, if a transaction is submitted while the Tire PRA is in "New" status, the transaction will reject for Error 7 (Tire Warranty Pre-Authorization Not Found).

Note: When returning tires, follow these steps:

- Use a tire crayon to mark the tire indicating the reason for replacement or location of the defect.
- A printed copy of the completed PRA and a copy of the Dealership/Retailer GWM Tire replacement form must be placed in an envelope and securely taped to each tire.

* IT IS THE DEALERSHIP/SERVICE AGENT RESPONSIBILITY TO CONTACT UPS AND INFORM THEM THAT THERE IS A TIRE(S) THAT NEED TO BE PICKED UP. Call 1-800-PICK-UPS (1-800-742-5877)

STEP FOUR: Monitor Status of PRA

Once the Tire Pre-Repair Authorization (PRA) is successfully submitted, the return document and shipping label are printed and the tire(s) shipped, the Status field shown on the PRA will move from "New" to "Accept" status the next business day.

If GWM does not require a tire return, the PRA will move from "New" to "Accept" the same business day the PRA is submitted.

Once a PRA is in "Accept" status, the service agent can submit the related transaction for payment. All normal transaction details are required. There is no way to submit a transaction directly from a PRA, or to transfer PRA information to a transaction. All job card information must be re-entered.

STEP FIVE: Submit the Transaction

Important: The Tire Pre-Repair Authorization (PRA) must be in "Accept" status before the service agent submits the warranty transaction. Failure to do so will result in the transaction being rejected for Error 007 (Tire Warranty Pre-Authorization Not Found.)

Transaction Field Details:

- Job Card Number and Date When submitting the transaction for payment, make sure these exactly match the job card number and date used in the Tire PRA. These fields must match the Accepted PRA for GWM to process the transaction for payment.
- Labour Operation Labour operations applicable to the New Vehicle Tire Warranty Program are included at the end of this bulletin. As with the job card number and date, the labour operation must match the one used in the Tire PRA.
- Part(s) Tires are to be submitted in the Parts Field for the FULL cost plus applicable warranty mark-up. Do not submit the prorated amount.
- Labour Submit the published labour time for mount and balance of the replacement tire(s).
- Net / Admin Allowance \$25 may be claimed for submitting the Tire Pre-Repair Authorization (PRA) into the Global Warranty Management (GWM) system and to return the tire(s) to the tire manufacturer.
- Customer/Service Agent Participation Submit in this field the customer's portion of the tire expense (cost plus mark-up) using the proration chart. This amount will then be deducted from the payment total.

Global Warranty Management — Sample Transaction Information

Transactions are submitted into GWM with the information as indicated below:

Repair Performed	Transaction Type	Labour Operation	Base Labour Time	Net Item/ Admin Allowance	Part Numbers	Net Item Types
Tire, Goodyear / Dunlop — Replace	ZREG	8060440	As Appropriate	\$25.00	All Detailed Parts	As Appropriate

Warranty Labour Codes and Time

Warranty Labour Codes and Time

OPERATION DESCRIPTION	*OE Tire Warranty Labour Operation Number	Labour Time
TIRE, GOODYEAR/DUNLOP— REPLACE	8060440	
TIRE, CONTINENTAL/GENERAL — REPLACE	8060460	
TIRE, MICHELIN, UNIROYAL, BF GOODRICH— REPLACE	8060480	
TIRE, BRIDGESTONE, FIRESTONE — REPLACE	8060540	Use Published Labour
TIRE, KUMHO — REPLACE	8060580	Operation Time
TIRE, HANKOOK — REPLACE	8060600	
TIRE, PIRELLI — REPLACE	8060620	
TIRE, MAXXIS — REPLACE	8060640	

Transportation Claims

For any tire replaced because of transportation damage or incorrect parts, use labour code 0500110 and submit as a transportation Transaction (ZTPT Transaction Type). Transportation transactions do not require the Pre-Repair Authorization (PRA) process prior to submission. **DO NOT use the Warranty Tire Replace Labour Codes** for any tire that is replaced due to transportation damage or incorrect parts.

Inspection Station Locations for Tire Returns

Please use these addresses to send the tires back to the OE Tire Manufacturer. Be sure to include the PRA document from GWM and the copy of the GWM Tire replacement form with the tire(s).

Inspection Station Locations for Tire Returns

Continental 12333 Airport Rd. Caledon, ON L7C 2X3	Hankook 30 Resolution Dr. Brampton, ON L6W 0A5
Goodyear North American Product Service Centre 450 Kipling Ave. Toronto, ON M8Z 5E1	Kumho Kumho Tire Canada Unit B, 6430 Kennedy Rd. Mississauga, ON L5T 2Z5
Michelin MNA CI Return Centre Att. Building 698 2863 Granton Rd. New Glasgow, NS B2H 5C6	Pirelli Pirelli Tire Inc.; c/o DB Schenker 6757 Northwest Dr. Mississauga, ON L4V 1L1
Bridgestone	Maxxis

Inspection Station Locations for Tire Returns (cont'd)

Pival International	
For: Bridgestone Canada Inc.	Cheng Shin Rubber, Maxxis
6611 Northwest Dr, Mississauga, ON	International — Canada 400–C Chrysler Dr.
L4V 1L1	Brampton, ON
Attn: Kevin Taylor	L6S 5Z5

Tire Companies & Contacts — Toll-Free Assistance

All replacement tires must be ordered through the GM National Account Tire Program.

Tire Companies & Contacts

Bridgestone Firestone Canada Inc., Integrated Client Service Dept., National Credit www.bridgestonetire.ca www.firestonetire.ca	Technical Service Manager (Gérant Service Technique) Bridgestone Canada Inc. 1300 Boul. Hymus Dorval, H9P1J6, QC. 1-877-685-3878 x.250 1-800-267-1318 1-514-685-3878
Continental General Tire Company www.generaltire.ca www.continentaltire.ca	Product Service Manager Passenger & Light Truck Tires Continental Tire Canada, Inc. Tel. Customer Relation: 1- 855-453-1962 1-905-568-1303 x.2225 6110 Cantay Road Mississauga, ON L5R 3W5

Tire Companies & Contacts (cont'd)

-	. ,
	Manager, Product Service Center
Goodyear Tire & Rubber Company www.goodyear.ca	Directeur du Centre de service des produits
	Toronto, Ontario
	1-416-201-7850
	1-800-387-3288
Michelin Tire Company (Includes Uniroyal and Goodrich) www.michelin.ca	Consumer Care Department 2500 Daniel Johnson, Suite 500 Laval, Québec H7T 2P6 1-888-871-4444
Kumho www.kumhotire.ca	Customer Service Arlene 1-877-445-8646 x111 Chris Thomas 1-403- 506-1591

Tire Companies & Contacts (cont'd)

Hankook (Remington Distributor) www.hankooktire.ca	Customer Service 1-800-843-7709
Pirelli www.pirelli.ca	Pirelli Tire Inc. 1111 boul. Dr. Frederik- Philips, suite 506 St- Laurent, Quebec H4M 2X6
	Quebec/Maritimes: 1-514- 331-4330; 1-800-363-0583; (514) 337-4033
	Ontario 1-800-828-2585 Fax: 1-800-519-8999
	Western Canada/Région de l'ouest: 1-800-663-0148 Fax: 1-800-519-8999
Maxxis www.maxxiscanada.com	1-905–789–0882

GM bulletins are intended for use by professional technicians, NOT a "<u>do-it-yourselfer</u>". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

