

## **Service Bulletin**

File in Section:

Bulletin No.: 18-NA-109

Date: April, 2018

# **TECHNICAL**

Subject: Transmission Fluid Leak, Right Front Wheel Drive Half Shaft Disengaged From Transmission

Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
Branu.	woder.	from	to	from	to	Engine:	
Chevrolet	Equinox	2018	2018			Equipped with 1.5L Engine (RPO LYK)	Equipped with 6 Speed Transmission (RPO MNH)

Involved Region or Country	North America and NA Export vehicles	
Condition	Some customers may comment on a transmission fluid leak.  Technicians may find that the right front wheel drive half shaft is disengaged from the transmission.	
Cause	This condition may be caused by the right front wheel drive half shafts that was installed during assembly being 7 mm short.	
Correction	Replace both the right side front wheel drive half shaft and seal.	

#### **Service Procedure**

Refer to Front Wheel Drive Half Shaft Replacement - Right Side in SI.

#### **Parts Information**

Causal Part	Description	Part Number	Qty
Χ	SHAFT ASM-FRT WHL DRV HALF	84305522	
	SEAL KIT-FRT WHL DRV SHF	24288436	1
	NUT,RR WHL DRV SHF	11611687	

### **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
3040080	Front Wheel Drive Half Shaft Replacement - Right Side	Use Published Labor Operation Time

Version	1
Modified	Released April 10, 2018

