



Technical Service Bulletin

01 "Reduce Oil Level" message in instrument cluster - 3.0T

01 18 61 2050690/2 March 22, 2018. Supersedes Technical Service Bulletin Group 01 number 18-59 dated March 8, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S4, S5	2017 - 2018	All	3.0T
SQ5	2018	All	3.0T

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Condition</i> (Updated structure) Revised <i>Warranty</i> (Updated Diagnostic Time)
1	03/08/2018	Initial publication

Customer states:

- "Reduce Oil Level" message shown in the instrument cluster.
- "Drive system: malfunction!" message shown in instrument cluster with engine rpm restriction.

Workshop findings:

- Engine oil level is **not** found to be over maximum using the dipstick. See ELSA for oil level specifications for each applicable model.

Note:

If engine oil level is found to be above MAX specification, this TSB does not apply. Correct the oil level per ELSA specifications and evaluate vehicle condition.

Technical Background

Software may be too sensitive to maximum oil level warning.

Production Solution

Software with improved oil level diagnostics in production.



Technical Service Bulletin

Service

SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the engine control module (ECM), J623 (address word 0001) using the SVM action code as listed in the table below, if necessary:

Model	Engine and/or Transmission	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Code Input
S4/S5 (all)	CWGD	8W0907559H	< 0008	8W0907559H	0008	01A234
SQ5	CWGD	80A907559C	< 0007	80A907559C	0007	01A234

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	Connect battery charger and perform software update with SVM	2470 2599	50 TU
Diagnostic Time:	Check oil level	1711 1999	10 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2050690/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

- TSB 2011732, *00 Software Version Management (SVM), operating instructions.*

All parts and service references provided in this TSB (2047707) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.