

# **Technical Service Bulletin**

#### 40 Noises from front end and dash panel, noise heard when the vehicle is moving

40 18 78 2047920/2 March 2, 2018. Supersedes Technical Service Bulletin Group 40 number 17-65 dated May 24, 2017 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, and Q7	2017 - 2018	All	Not Applicable

## Condition

REVISION HISTORY			
Revision	Date	Purpose	
2	-	Revised title (Added clarity) Revised Additional Information (Updated disclaimer)	
1	05/24/2017	Initial publication	

#### **Customer states:**

 There is a buzzing, booming, humming, whistling or a similar noise from the front end. The noises can possibly be heard from the area the steering or behind the dash panel. The noises may also suspected to be tire rolling noises.

#### Workshop findings:

• The noises can be reproduced in a test drive.

### **Technical Background**

Mechanical damage on the wheel bearing of the front axle.

## **Production Solution**

Not applicable.

### Service

The noises from the wheel bearing can be transmitted via the steering into the vehicle interior. Because of the close proximity it can be difficult to distinguish them from tire rolling noises.

Page 1 of 3

<sup>© 2018</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## Technical Service Bulletin

Therefore with such noises check whether the wheel bearings of the front axle may be the source and replace the affected component. The following steps are helpful:

- 1. Does the frequency rise as the speed increases or does the sound get higher?
- 2. Does the noise get louder when steering?
- 3. Is the noise still there when slowing down?
- 4. Is the noise amplified on the steering wheel/airbag well?
- 5. Can the vibrations be felt on the unpressed coil spring when the wheel is turning?
- 6. When swapping around the wheel bearings does the noise move with a particular bearing?

**Tip:** Please precisely locate the source of the noise with acoustic testers. It is possible that a noise perceived on the left side of vehicle is caused by the right wheel bearing. The front wheel bearings should not be replaced in pairs.

If the cause of the noise cannot be traced to a wheel bearing, continue the analysis on other components.

#### Warranty

Claim Type:	<ul> <li>110 up to 48 Months/50,000 Miles.</li> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> </ul>		
	If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4057		
Damage Code:	0020		
Labor Operations:	A4 & A5 one front wheel bearing:		
	Remove and install front hub with bearing	4067 1900	80 TU
	Replace front wheel bearing	4057 5550	40 TU
	A4 & A5 both front wheel bearings:		
	Remove and install 2 front hubs with bearings	4067 2000	140 TU

© 2018 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## Technical Service Bulletin

	Replace 2 front wheel bearings	4057 5650	70 TU
	Q7 one front wheel bearing:		
	Remove and install front hub with bearing		90 TU
	Replace front wheel bearing	4057 5500	130 TU
	Q7 both front wheel bearings:		
	Remove and install both front wheel bearings	4067 2000	160 TU
	Replace 2 front wheel bearings	4057 5600	230 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2047920/2		

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

### **Required Parts and Tools**

Part Number	Part Description	Quantity
See ETKA	Wheel bearings	(Up to 2)

### **Additional Information**

All parts and service references provided in this TSB (2047920) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

<sup>© 2018</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.