

## **Service Bulletin**

File in Section:

Bulletin No.: 18-NA-012

Date: January, 2018

# **TECHNICAL**

Subject: No Click Heard or No Crank From the Starter, No Start

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado Models	2017	2018				
	Suburban						MVC
	Tahoe						MYC
GMC	Sierra Models						

Involved Region or Country	North America and Middle East
Condition	Some customers may comment that the vehicles starter does not click/crank when trying to start or that vehicle does not start.
0	This condition may be caused by an open Park/Neutral circuit within the control valve solenoid assembly.
Cause	⇒ This concern may be dependent on the ambient temperature of the transmission oil.
	The P/N circuit should be normally grounded through the control valve solenoid when the transmission is in Park or Neutral.
Correction	If a no start / no crank condition is encountered, check for an open circuit within the transmission on Circuit 1786, Transmission connector X1, Terminal 3 (WH/GY wire). This circuit should be normally closed (grounded) when the transmission is in Park or Neutral.
	If an open circuit is found and the wire from the transmission connector to the control valve solenoid has continuity, replace the control valve solenoid.

#### **Service Procedure**

Refer to Control Solenoid Valve and Transmission Control Module Assembly Replacement in SI.

#### **Parts Information**

Causal Part	Description	Part Number	Qty
Х	VALVE, CONT SOL	24275873	1
	FLUID, A/TRANS (Dexron)	Refer to EPC	

### **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time	
8463730	Control Solenoid Valve and Transmission Control Module Assembly Replacement	Use the Published Labor Operations Time	

Version	1
Modified	Released January 16, 2018