

## Service Bulletin

File in Section:

Bulletin No.: 18-NA-014

Date: January, 2018

# **TECHNICAL**

Subject: Malfunction Indicator Lamp Illuminated, DTC P2096 Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Eligille.	mansinission.
Chevrolet	Malibu (VIN Z)	2016	2016	_	_	1.8L (RPO LKN)	5ET50 (RPO MKE)

Involved Region or Country	United States, Canada, Israel		
Condition	Some customers may comment that the Malfunction Indicator Lamp (MIL) is illuminated. The technician may find DTC P2096 set.		
Cause	This condition may be caused by a software anomaly in the engine control module (ECM).		
Correction	Updated software has been released to address this condition. If you encounter a vehicle with the above condition, reprogram the ECM with the latest available software.		

#### **Service Procedure**

- 1. Ignition ON.
- 2. Perform the Diagnostic System Check Vehicle.
- Verify that no other HO2S or Fuel Trim DTCs are set.
  - ⇒ If any other HO2S or Fuel Trim DTCs are set, go to Diagnostic Trouble Code (DTC) List -Vehicle.
  - ⇒ If only DTC P2096 is set, go to Step 4.

**Important:** Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

4. Reprogram the ECM with the latest available software. Refer to *K20 Engine Control Module: Programming and Setup* in SI.

#### **Parts Information**

No parts are required for this repair.

### **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time	
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time	

#### **Version Information**

Version	1
Modified	Released January 16, 2018

