

Service Bulletin

File in Section:

Bulletin No.: 18-NA-018

Date: January, 2018

TECHNICAL

Subject: Brief Crank and No Start Followed by No Crank Until ECM Powers Down

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	Transmission:
	Envision (China Only)	2015	2015	All	All	2.0L — RPO LTG	_
Buick	Envision (United States, Canada, Mexico and China)	2016	2016	All	All	2.0L — RPO LTG	_

Involved Region or Country	United States, Canada, Mexico and China		
Condition	Some customers may comment that the engine exhibits a brief crank and it will start and rev up and then it quits running. That condition is followed by a no crank until they wait for some time to allow the ECM to power down.		
Cause	This condition may be caused by a software anomaly in the engine control module (ECM).		
Correction	Updated software has been released to address this condition. If you encounter a vehicle with the above condition, reprogram the ECM with the latest available software.		

Service Procedure

- 1. Ignition ON.
- 2. Perform the Diagnostic System Check Vehicle.
 - ⇒ If any DTCs are set, go to Diagnostic Trouble Code (DTC) List - Vehicle.
 - ⇒ If no DTCs are set, go to Step 3.

Important: Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install the EL-49642 SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

In China, use the recommended equivalent workshop equipment for the SPS Programming Support Tool.

3. Reprogram the K20 Engine Control Module with the latest available software. Refer to *K20 Engine Control Module: Programming and Setup* in SI.

Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time

Page 2 January, 2018 Bulletin No.: 18-NA-018

Version Information

Version	1
Modified	Released January 19, 2018