

Service Bulletin

File in Section:

Bulletin No.: 18-NA-022

Date: January, 2018

TECHNICAL

Subject: Instrument Cluster Goes Blank or Tell Tale Indicators Remain On

Brand:	Model:	Model Year:		VIN:		Funina	Transmission:
		from	to	from	to	Engine:	
Buick	Enclave	2018	2018	June 19, 2017	September 20, 2017	All	All
Buick	Envision	2018	2018	May 15, 2017	September 14, 2017	All	All
Cadillac	XT5	2018	2018	April 27, 2017	August 14, 2017	All	All
Chevrolet	Corvette	2018	2018	March 2, 2017	July 27, 2017	All	All
Chevrolet	Suburban	2018	2018	May 23, 2017	August 21, 2017	All	All
Chevrolet	Tahoe	2018	2018	May 24, 2017	August 21, 2017	All	All
GMC	Acadia	2018	2018	April 21, 2017	August 14, 2017	All	All
GMC	Sierra	2018	2018	April 25, 2017	August 17, 2017	All	All
GMC	Yukon	2018	2018	May 22, 2017	August 21, 2017	All	All
GMC	Yukon XL	2018	2018	May 23, 2017	August 21, 2017	All	All

Involved Region or Country	North America and N.A. Export Regions	
Additional Options (RPOs)	Equipped with RPO UHS Instrument Cluster	
Condition	Some customers may experience a condition in which the center of the instrument cluster goes blank upon startup and will remain blank the entire drive cycle; or that tell tale indicators may illuminate in the instrument cluster at startup and remain on the entire drive cycle or until a command is sent to re-activate the tell tale.	
Cause	This may be due to a software anomaly.	
Correction	Reprogram the cluster.	

Service Procedure

If you encounter a vehicle with the above concern, reprogram the cluster. Refer to *P16 Instrument Cluster: Programming and Setup* in SI.

Parts Information

No parts are needed for this condition.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time

Page 2 January, 2018 Bulletin No.: 18-NA-022

Version	1
Modified	Released January 22, 2018