

# Service Update

## 18088 Incorrect Engine Oil Fill Cap



Reference Number: N182154360

Release Date: March 2018

Revision: 00

**Attention:** This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

| Make      | Model    | Model Year |      | RPO | Description |
|-----------|----------|------------|------|-----|-------------|
|           |          | From       | To   |     |             |
| Chevrolet | Corvette | 2019       | 2019 |     |             |

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

|                   |   |
|-------------------|---|
| <b>Condition</b>  | Certain 2019 model year Chevrolet Corvette vehicles may have been built with an incorrect 5W-30 labeled engine oil fill cap instead of the correct 0W-40 labeled cap. |
| <b>Correction</b> | Inspect for incorrect cap and replace if needed.  |

### Parts

| Quantity | Part Name               | Part No. |
|----------|-------------------------|----------|
| 1        | Cap Assembly – Oil Fill | 12686472 |

It is estimated that only 284 involved vehicles will require parts replaced on this vehicle. Due to the small number of vehicles anticipated that will need this fix and the limited initial parts availability, dealers are encouraged not to order recall parts for use as shelf stock.

**Reminder:** Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

### Warranty Information

| Labor Operation | Description                         | Labor Time | Trans. Type | Net Item |
|-----------------|-------------------------------------|------------|-------------|----------|
| 9103729         | Replace Engine Mounted Oil Fill Cap | 0.2        | ZFAT        | N/A      |

### Service Procedure



5019913

1. Raise the vehicle hood and locate the oil fill cap installed on the driver side of the engine.

## Service Update

### 18088 Incorrect Engine Oil Fill Cap



5019920

2. Remove the existing fill cap (marked SAE 5W-30) and install the new service fill cap with the correct SAE 0W-40 specification printed on top.

#### Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin must be held and inspected/repaired per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support  
Voluntary Technician  
Certification**

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4691  
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 19, 2018

Subject: 18088 – Service Update  
Incorrect Engine Oil Fill Cap

Models: 2019 Chevrolet Corvette

To: All General Motors Dealers

General Motors is releasing Service Update 18088 today. The total number of U.S. vehicles involved is approximately 284. Please see the attached bulletin for details.

**Global Warranty Management (GWM)**

The Investigate Vehicle History (IVH) screen in the GWM system will be updated March 19, 2018. A list of involved vehicles is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS