ATTENTION:


GENERAL MANAGER

PARTS MANAGER

CLAIMS PERSONNEL

SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



© 2018 Subaru of America. Inc. All rights reserved.

QUALITY DRIVEN® SERVICE

SUBARU

SERVICE INFORMATION BULLETIN

APPLICABILITY: 2016-2018MY Forester NUMBER: 04-20-18

2015-2016MY Impreza 2.0L DATE: 05-31-18

SUBJECT: Steering Angle Sensor- Part Change Information

INTRODUCTION:

This Service Information bulletin announces a running change made to the Steering Angle Sensor. The (new) -style originally used on Legacy and Outback has been adapted for use on the additional models listed above.

PRODUCTION CHANGE INFORMATION:

The new-style sensors were incorporated into production during May / June of 2015. During that production time frame, either an old-style or new-style sensor may have been installed. The starting VINs below are for vehicles identified as after the change-over to the new-style sensor.

Forester: G*406546
Impreza: F*019429
Crosstrek: F*296078

PART INFORMATION:

The photos below show the most easily identifiable features to the Steering Angle Sensor to help differentiate between the old and new-style parts.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.



SERVICE PROCEDURE / INFORMATION:

The service procedures for diagnosing and replacing the Steering Angle Sensor are unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time. This includes but is not limited to: important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and any related one-time-use parts information needed for a complete and lasting repair. Customer satisfaction and retention starts with performing quality repairs.

IMPORTANT: When Sensor replacement is necessary on a model applicable to this bulletin, always replace the old part with the same style as originally equipped. Once inventory of the old-style part has been exhausted, the old part number, 27589AJ000 will be superseded to 27549AL000.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.