

Subject MIL ON P314A and/or P0C73, Corrosion Present in A9 Inverter Water Pump Connector		Market USA
Service Category Vehicle Interior	Section Meter/Gauge/Display	
Applicability 14-16MY Highlander HV14-2016MY Highlander HV		

APPLICABLE VEHICLES


2014-2016

Highlander HV


CONDITION

Vehicles may experience a MIL ON condition exhibiting codes P314A and/or P0C73 with evidence of water (corrosion) at the A9 inverter water pump connector. This condition may be caused by vehicles being equipped with an aftermarket windshield assembly with a poorly sealed or damaged deicer harness.

Water can enter in through deicer harness, wick down to the common shared ground junction A72 and then wick from the A72 ground connector to inverter water pump connector.



Windshield Deicer Harness (Located in cowl area):



Subject

MIL ON P314A and/or P0C73, Corrosion Present in A9 Inverter Water Pump Connector

Market

USA

Applicability

Aftermarket deicer connection at windshield example:



Toyota genuine deicer connection at windshield harness example:



RECOMMENDATIONS

If corrosion is found at the A9 inverter water pump connector, the following is recommended:

- 1) Inspect A33 windshield deicer connection-to-engine main wire harness for evidence of corrosion.
- 2) Check if windshield is non-genuine Toyota windshield. Toyota genuine windshields will have a "Toyota" marking on label and a Toyota part number on the deicer harness. The deicer harness and windshield come as an assembled unit.
- 3) Toyota recommends that windshields only be replaced with Toyota genuine parts. Toyota genuine windshields are equipped with seals for prevention of water intrusion to the engine room main wire harness.
- 4) If corrosion is found in the A33 connector and the windshield is a Toyota genuine part, please contact TAS.

LINK REFERENCES

This Tech Tip does not contain any link references