Reference	SSM73067
Models	F-TYPE / X152 XF / X250 XJ / X351 XK / X150
Title	3.0L & 5.0L Supercharger Noise post TSB VIN's
Category	Engine
Last modified	10-May-2018 00:00:00
Symptom	497000 Engine Noise
Content	 Issue: JLR is investigating 3.0L & 5.0L Supercharger noise, post VIN's on JTB00349v2 & JTB00356v2. F-Type - K10800 XJ - V65921 XF U21817 Cause: No fault identified to date. JLR engineering investigation is underway.
	 Action: Please remove the S/C drive belt to see if the noise disappears. If it remains, please continue to investigate the source of the noise. If the noise disappears, refit the drive belt and run the below test 'Noise, Vibration & Harshness test - Accessory drive belt.
	Noise, Vibration & Harshness test - Accessory drive belt Diagnostic procedure:
	Select the following symptoms:
	Powertrain - Engine system - Engine performance - Noise Run the following candidate:
	 Special applications - Noise, Vibration & harshness sensor diagnostic test - Accessory drive belt - ID 70710 NOTE: DO NOT replace any parts if the 'Accessory belt NVH procedure' application requests you to do so. This exercise is purely for data gathering purposes only, as no specific S/C NVH sensor application is available at present.
	If the noise is believed to be from the supercharger unit, then proceed

to change the complete unit assembly, and retain it for priority returns request. Please then send an email to corr@jaguarlandrover.com &

cbradle5@jaguarlandrover.com with reference to SSM73067

and submit an ePQR.

r

Thank you in advance for your assistance in this matter.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

- 1 = Poor Basic information provided The SSM does not help me resolve the customer concern.
- 3 = Average Adequate information provided The SSM partially helps me resolve the customer concern.
- 5 = Excellent All required information provided to resolve the customer concern.