

Reference	SSM73886
Models	E-PACE / X540
Title	X540 E-Pace, Instrument panel - tyre pressure information not displayed
Category	Electrical
Last modified	25-May-2018 00:00:00
Symptom	204000 Instrumentation
Attachments	SSM-73886_IP-Attachment_menu button and pictures.pdf

ContentIssue:

Instrument panel - tyre pressure information not displaying recommended pressure in brackets (see photo 1, example attached).

Affected Vehicle line:

X540 E-Pace, MY2018

VIN Range:

Start VIN: **SADFA2BX3J1Z25580**

End VIN: TBD

Cause:

Software error.

Action:

If a customer reports that the recommended tyre pressure is not shown on the instrument panel the following advice should be given to them.

Communication to Customer:

- JLR is aware of the concern which is preventing the displaying of information on the instrument cluster.
- This information can still be viewed both through the Instrument Panel by following the process highlighted below and on the tyre placard label on the driver's door aperture.

Refer to owner manual, section:

*Tyre Pressure Monitoring System (TPMS) -> **INSTRUMENT PANEL MENU***

Operate as follows:

1. MENU button: Press "OK" to display the instrument panel menus.
2. Select Vehicle info
3. Select Tyre information
4. Select Recommended pressure (photo 2, example attached)

- Light load / Heavy Load level will be displayed

Note: The TPMS will still provide a low pressure warning

See attachment to SSM for menu button and pictures

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.