

**Panamera 4 E-Hybrid (971) Cooling System Fault POC4A00**

**Vehicles Affected**

Model	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Panamera 4 E-Hybrid	2018	971	N/A	N/A

**Revision History**

Revision	Release Date	Changes
0	May 24, 2018	Original document

**Condition**

The customer experiences a MIL. The workshop confirms this and observes fault code POC4A00.

**Technical Background**

The coolant pump for the high voltage battery actively monitors its own speed and current consumption. For a given commanded speed, if the actual pump speed exceeds a defined value and the current consumption drops below a certain threshold, a dry run condition is detected. The pump communicates this to the high voltage battery control unit and fault code POC4A00 is stored. One possible cause of this is air in the low temperature cooling system. This fault can take several hundred miles to set.

**Service Information**

- 1) Check for air in the low temperature cooling system:
  - a) With the ignition off and the system cool, remove the cap of the low temperature cooling system reservoir. Observe and record the coolant level in the reservoir.
  - b) Pressurize the low temperature cooling system to 1.0 Bar using the cooling system pressure tester. Record the approximate amount the coolant level dropped when system is under pressure.
  - c) If there is no air in the system, the coolant level will only drop approximately 4 to 7 mm. (This will vary with factors such as system temperature.)
  - d) If while under pressure, the coolant level drops more than approximately 7 mm, there is likely air in the system and it needs to be bled. (See figures 1 and 2.)



Figure 1

**Service Information (continued)**

2) Bleed the low temperature cooling system:

**Note:** This process is not a substitute for the draining and filling process in the workshop manual. If the low temperature cooling system is ever opened due to component removal, the Workshop Manual must be followed: WM 193817 Draining and filling coolant (low-temperature cooling system).

- a) Leave the low temperature cooling system under 1.0 Bar of pressure using the cooling system pressure tester.
- b) Run the Low-temperature cooling bleeding/ventilation process 3 times using the PT3G Tester: Thermal Management -> Drive links checks -> Low-Temperature cooling system ->Ventilate cooling system




Figure 2

3) Verify successful bleeding:

- a) Relieve all pressure from the low temperature cooling system and record the coolant level in the reservoir.
- b) Apply 1.0 Bar of pressure to the low temperature cooling system using the cooling system pressure tester.
- c) Observe the approximate level drop of the coolant when pressure is applied. If the coolant level only drops about 4 to 7mm when under pressure, there should no longer be any air in the system. (See figure 3.)
- d) If this process is unsuccessful at removing the air, follow WM 193817 Draining and filling coolant (low-temperature cooling system).




Figure 3

**Warranty**

As always, be sure to document the repair completely in PQIS. For this repair, please code the "cause" as follows:

Cause location: 2708A HV battery cooling line

Cause symptom: 5021 Not airtight

**Search Items**

Panamera 4 E-Hybrid; Breakdown; MIL; POC4A00; cooling line

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.