

TO: Hyundai Dealership General Managers, Sales Managers,
Service Managers, Parts Managers, and Warranty
Administrators
FROM: Hyundai Motor America
DATE: June 12, 2018
SUBJECT: Service Campaign T3A - 2018 Elantra V-Ribbed Belt
Inspection and Replacement (TSB# 18-01-022)

Hyundai Motor America is conducting a Service Campaign to inspect and (if necessary) replace the V-ribbed belt on certain 2018 2.0L Elantra vehicles. Service Campaign T3A provides a service procedure to inspect the V-ribbed belt.

In order to identify only those vehicles affected by Service Campaign T3A, it will be necessary to access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS before starting the inspection. The "Warranty Vehicle Information" screen will identify affected vehicles with an open Service Campaign T3A.

A listing of VEHICLES is also located on WEBDCS, SERVICE tab, select INFORMATION, and select UNCOMPLETED CAMPAIGN VIN LISTING - Dealer Stock & Retailed.

TSB #18-01-022 will be available on HMAService.com on June 12, 2018. It contains instructions on performing the service procedure and submitting the campaign claim.

It is IMPORTANT TO SUBMIT A CAMPAIGN CLAIM FOR EACH VEHICLE SERVICED so your dealership can be compensated for your work and Hyundai can maintain accurate records of campaign completions.

LEGAL LIABILITY NOTICE: Hyundai Motor America dealers may use owner information provided for the campaign only for the purpose of conducting and performing this service campaign, and for no other purpose, including marketing to affected owners. You may not disclose any such information to others.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA