


| | | |
|--|--|--|
| DISTRIBUTE TO: <input checked="" type="checkbox"/> Service Manager <input checked="" type="checkbox"/> Warranty Administrator |  TOYOTA Warranty Policy Bulletin | No.: POL17-01 Date: 03/16/2017 Page: 1 of 5 REVISED 07/06/17 |
|--|--|--|

**SUBJECT: WARRANTY ENHANCEMENT PROGRAM (ZG5):
 WARRANTY EXTENSION FOR OVERHEAD CONSOLE
 SWITCH ASSEMBLY ON CERTAIN 2012 MY CAMRY AND
 CAMRY HYBRID AND 2011–2013 MY SIENNA VEHICLES**

Background

Toyota has received reports of customer concerns in which the power moon roof, power sliding doors or power hatch are inoperative from the overhead console switches or require excessive pressure on the overhead console switches to operate.

Due to parts availability this Warranty Enhancement Program will be launched in 2 phases as illustrated below:

| Phase | Model | Model Year | Dealer Announcement Schedule | Status |
|-------|------------------------|-------------------|------------------------------|------------------|
| 1 | Camry and Camry Hybrid | Certain 2012 | March, 2017 | Repair Available |
| 2 | Sienna | Certain 2011-2013 | June, 2017 | Repair Available |

Applicability

The Overhead Console Switch Assembly is covered by Toyota’s New Vehicle Limited Warranty* for 3 years or 36,000 miles (whichever occurs first). However, Toyota is announcing a Warranty Enhancement Program to cover repairs related to the Overhead Console Switch Assemblies that become inoperative or require excessive pressure to operate.

Primary Coverage offers the Warranty Enhancement until **September 30, 2018, with no mileage limitation.**

After the Primary Coverage period ends, the **Secondary Coverage** is applicable for **nine (9) years from the date-of-first use, or 120,000 miles, whichever occurs first.**

Verify VIN applicability for this Warranty Enhancement by checking TIS before completing any repairs.

Applicability (Continued)

Direct marketing of this Warranty Enhancement is strictly prohibited pursuant to the Toyota Warranty Policy 5.21, "Warranty Solicitation." Non-compliance of this policy may result in a claim debit.

****This Warranty Enhancement Program is subject to all of the terms and conditions set forth in the Toyota New Vehicle Limited Warranty. For example, damage from abuse, an accident, theft and/or vandalism, or repairs to vehicles which are currently or were previously titled as "scrap," "salvage," or "dismantled" is not covered by the New Vehicle Limited Warranty or this Warranty Enhancement pursuant to Warranty Policy 4.17, "What Is Not Covered by the Toyota New Vehicle Limited Warranty".***

Covered Vehicles

Not all vehicles are covered by this warranty enhancement. Verify VIN applicability for this warranty enhancement by checking TIS before completing any repairs.

Technician Training Requirements

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this repair are required to currently hold at least one of the following certification levels:

- Certified
- Expert
- Master or Master Diagnostic Technician (MDT)

Claims for repairs that were performed by non-qualified technicians are subject to debit.

Please ensure this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.

Claim Submission

| Claim Type | Model | Opcode | Description | Labor Time |
|----------------|----------|--------|---------------------------------------|-----------------|
| Repair Program | Sienna | BHG39A | Replace the roof console box assembly | 0.2 hr./vehicle |
| | Camry | BHG39B | | 0.4 hr./vehicle |
| | Camry HV | | | |

Note: If the vehicle is still under the New Vehicle Limited Warranty, submit the repair as a **Regular** warranty claim.

Please ensure this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.

Replacement Parts

All parts replaced for this repair are subject to warranty parts recovery.

| Model | Service Part Number | Kit Part Number | Description | Qty |
|---------------------|---------------------|-----------------|----------------------------------|-----|
| Sienna | 63650-08161-B0 | 04005-55108-B0 | SSP BOX ASSY, ROOF CONSOLE | 1 |
| | 63650-08161-E0 | 04005-55108-E0 | | |
| | 63650-08441-B0 | 04005-55208-B0 | | |
| | 63650-08441-E0 | 04005-55208-E0 | | |
| | 63650-08181-B0 | 04005-55308-B0 | | |
| | 63650-08181-E0 | 04005-55308-E0 | | |
| | 63650-08461-B0 | 04005-55408-B0 | | |
| | 63650-08461-E0 | 04005-55408-E0 | | |
| | 63650-08491-B0 | 04005-55508-B0 | | |
| | 63650-08491-E0 | 04005-55508-E0 | | |
| | 63650-08171-B0 | 04005-55608-B0 | | |
| | 63650-08171-E0 | 04005-55608-E0 | | |
| | 63650-08451-B0 | 04005-55708-B0 | | |
| | 63650-08451-E0 | 04005-55708-E0 | | |
| | 63650-08191-B0 | 04005-55808-B0 | | |
| | 63650-08191-E0 | 04005-55808-E0 | | |
| | 63650-08471-B0 | 04005-55908-B0 | | |
| | 63650-08471-E0 | 04005-55908-E0 | | |
| | 63650-08481-B0 | 04005-56108-B0 | | |
| | 63650-08481-E0 | 04005-56108-E0 | | |
| 63650-08421-B0 | 04005-56208-B0 | | | |
| 63650-08421-E0 | 04005-56208-E0 | | | |
| 63650-08431-B0 | 04005-56308-B0 | | | |
| 63650-08431-E0 | 04005-56308-E0 | | | |
| Camry & Camry HV | 63650-06422-A0 | - | BOX ASSY, ROOF CONSOLE | 1 |
| | 63650-06422-B0 | | | |
| | 63650-06432-A0 | | | |
| | 63650-06432-B0 | | | |
| | 63650-06442-A0 | | | |
| | 63650-06442-B0 | | | |
| | 63650-06450-A0 | | | |
| 63650-06450-B0 | | | | |

Technical Instructions (Repair Procedures)

For Camry and Camry Hybrid, technical instructions can be found in T-SB-0116-14. For Sienna, technical instructions can be found in T-SB-0170-13. Please refer to TIS for additional information.

Please ensure this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.

Customer-Paid Repairs or Replacement of Components

If a customer has previously paid for the repair to address the condition described above, please have them mail a copy of the repair order, proof-of-payment, and proof-of-ownership to the following address for reimbursement consideration:

**Toyota Customer Experience Center - TSR
Toyota Motor Sales, USA, Inc.
c/o Toyota Motor North America, Inc.
P O Box 259001 – SSC/CSP Reimbursements
Plano, Texas 75025-9001**

The customer name, address, and telephone number(s) should be included in the request. The customer should allow 4-6 weeks for processing.

Please ensure this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.