



## SERVICE ACTION H070: ADAPTIVE DAMPING (AD) WARNING MESSAGE

## SERVICE BULLETIN

27-JUN-18

NO.: 6-393NAS

SEC.: GENERAL  
INFORMATION

MKT.: CAN / USA

### DESCRIPTION OF ISSUE

An issue has been identified on a limited number of Jaguar vehicles within the listed Affected Vehicle Range may display an Adaptive Damping (AD) warning message on the Instrument Cluster. Investigations have identified that on occasion, the Diagnostic Trouble Code (DTC) U3000-04 may be stored in the Chassis Control Module (CHCM), which will lead to the warning message being displayed. The warning message will remain present until the ignition has been cycled OFF and ON; however, the warning message will be displayed again until the software update below is performed.

### AFFECTED VEHICLE RANGE

F-PACE (X761; with Adaptive Damping)

Model Year: ..... 2018

VIN: ..... 240014-290168

Visit the Jaguar Business Network (JBN) website for a list of affected unsold vehicles (as of 26 June 2018).

### SERVICE PROGRAM / REWORK ACTION

Retailers will update Chassis Control Module (CHCM) software to the latest level. There will be no charge to owners for this action under this program.

### ACTION TO BE TAKEN

Use the Jaguar Land Rover claims submission system to ensure that the vehicle is affected by this Program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin H070NAS, *Service Action: Adaptive Damping (AD) Warning Message*, for detailed repair instructions.

### PARTS

No parts required.

### TOOLS

Refer to the Technical Bulletin referenced above for any required special tools.

### WARRANTY

**NOTE: use the Jaguar Land Rover claims submission system to ensure that a vehicle is affected by this program prior to undertaking any rework action.**

At the time of confirming a booking for vehicle repair, ensure that all outstanding Recall and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information listed have been included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to the Jaguar Land Rover claims submission system to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the 31 December 2019 closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS / SUNDRY CODE	QTY. / VALUE
<b>H070</b>	<b>A</b>	Update ECU - Chassis Control Module (CHCM)	86.98.47	0.2	-	-
<b>H070</b>	<b>B</b>	Update ECU - Chassis Control Module (CHCM)	86.98.47	0.2	-	-
		Drive in/drive out	10.10.10	0.2	-	-

*Normal Warranty policies and procedures apply.*