

**Symptom - Engine - Warning Message "Refill Coolant Immediately! Do Not Drive On" in Instrument Cluster: Replacing coolant reservoir (SY 62/18)**

Vehicle Type: **718 Boxster/718 Cayman (982)**

Model Year: **As of 2017 up to 2018**

Symptom: **The red warning message "Refill coolant immediately! Do not drive on" can appear at times in the instrument cluster.**

⇒ (Warning message: "Refill coolant immediately!")



(Warning message: "Refill coolant immediately!")

Cause: Due to an error during production (of the "locking lug"), the electric plug connection on the coolant reservoir cannot be locked correctly.

Remedial Action:



**Information**

In the event of a complaint and if the plug connection is loose, the coolant reservoir **must** be replaced, see ⇒ *Workshop Manual '194019 Removing and installing coolant reservoir'*.

⇒ **It is not enough to just re-connect the electric plug connection to the existing coolant reservoir.**

Date of Introduction: An adapted coolant reservoir has been installed as standard since April 10, 2018 or as of vehicle identification number WPOCA2982JS212001.

Parts Info:

**Information**

The following points must be observed in relation to the part numbers listed below and the relevant vehicle (depending on equipment):

- **Particular/modified components**, whose part numbers are listed accordingly, are **required for the remedial action**.
- **Part number indexes will increase over time**. Before performing repairs, cross reference with PET (Porsche Spare Parts Catalog), for newer parts (higher index).
- **PET must be checked** to determine if additional components are needed.

**982.121.407.C** ⇒ Coolant reservoir

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
19401950	Removing and installing reservoir	

For invoicing and documentation using PQIS, enter the following coding:

<b>Location (FES5)</b>	19110	Engine coolant level sensor
<b>Damage type (SA4)</b>	4021	Incorrect signal

References: ⇒ *Workshop Manual '194019 Removing and installing coolant reservoir'*

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© Porsche Cars North America, Inc.