



Bulletin No.: PIC6337

Published date: N/A

Preliminary Information

PIC6337 Rattle Noise from Exhaust

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Camaro	2018	All	All	LGX	All

Involved Region or Country	North America
----------------------------	---------------

Additional Options (RPO)	NPP - Dual Mode Exhaust
--------------------------	-------------------------

Condition

Some customers may comment about an exhaust rattle coming from the vehicle. Many technicians will automatically look at the exhaust valves for noise concerns. Before any repair is made, dealership technicians should also look at the resonator for the source of this concern. There is a tube that is located in the center of the resonator that can be seen in the first photo below. This is NOT a drain tube for condensation inside the exhaust system. This pipe is actually a structural component of the resonator that stiffens the upper and lower halves of the assembly. The welds holding this tube in place may crack, resulting in a rattle noise that can be heard by the owner of the vehicle. This will be most noticeable when starting the engine / applying the throttle.

Note: Corrosion alone will not cause this concern. The quality of the actual welds is the issue. Dealership technicians are to inspect both the lower weld on the bottom of the resonator, as well as the upper weld on top of the resonator for signs of cracking.





Correction:

If the concern listed above has been found, dealership technicians are to replace the rear portion of the exhaust system.

Warranty Information

Labor Operation	Description	Labor Time
4051530	Exhaust Muffler Replacement	Use Published Labor Time
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	Created on 07/18/2018



© 2018 General Motors. All Rights Reserved.