

Paint Bubbles in Carbon Fiber Parts

Vehicles Affected

Model	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
911 Turbo S	2018	991	N/A	N /A
911 GT2 RS	2018	991	N/A	N/A

Revision History

Revision	Release Date	Changes
0	July 11, 2018	Original document

Customer Concern

Customer complains of bubbles in the paint on carbon fiber parts.



Technical Background

Bubbles are caused by contamination during the paint process.

Service Information

There is no paint repair solution. The carbon fiber components with the issue must be replaced.

Production Information

Cleanliness measures to prevent contamination are being optimized. No vehicles with this issue have come out of production since January 2018.

Search Items

Paint bubbles; paint flaw; paint defect; carbon fiber; painted carbon fiber

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
