



TECHNICAL SERVICE BULLETIN

6.7L - Coolant Pump Leak - Built On Or Before 1-Jun-2017

18-2194
05 July 2018

Model:

Ford 2015-2017 F-Super Duty

Issue: Some 2015-2017 F-Super Duty vehicles equipped with a 6.7L engine built on or before 1-Jun-2017 may exhibit a leak from the coolant pump.

Action: Follow the Service Procedure steps to correct the condition.

Parts

Part Number	Description	Quantity
HC3Z-8501-A	Coolant Pump	1
VC-3DIL-B	Motorcraft® Orange Prediluted Antifreeze/Coolant	8

Warranty Status: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2015-2017 F-Super Duty 6.7L: Diagnose And Replace The Primary Coolant Pump (Do Not Use With Any Other Labor Operations)	182194A	3.1 Hrs.

Repair/Claim Coding

Causal Part:	8501
Condition Code:	D8

Tool List

Drive	Tool Name
1/4"	Power Tool
1/4"	Ratchet
1/4"	Torque Wrench
1/4"	7 mm Socket
1/4"	8 mm Socket
1/4"	10 mm Socket
3/8"	Power Tool
3/8"	Ratchet
3/8"	Torque Wrench
3/8"	13 mm Socket
	8 mm Ratchet Wrench
	Metal Push Pin Tool
	Motion Pro Torque Adapter

Service Procedure

1. Allow the engine to cool before checking the engine coolant level. Visually inspect the engine coolant level at the degas bottle. Is the engine coolant level low?
 - (1). Yes - proceed to Step 2.
 - (2). No - this article does not apply. Refer to Powertrain Controls/Emissions Diagnosis (PC/ED) Manual or Workshop Manual (WSM), Section 303-03C for normal diagnostics.
2. Visually inspect the engine coolant for contamination. Is the engine coolant contaminated?
 - Note: Engine coolant system flushing is not required during coolant pump removal and installation. During normal vehicle operation, Motorcraft® Orange Prediluted Antifreeze/Coolant may change color from orange to pink or light red. As long as the engine coolant is clear and uncontaminated, this color change does not indicate the engine coolant has degraded nor does it require the engine coolant to be drained and replaced or the cooling system to be flushed.
 - (1). Yes – this article does not apply. Refer to WSM, Section 303-03C.
 - (2). No - proceed to Step 3.
3. Perform a pressure test of the engine cooling system. Refer to Component Tests, Cooling System Pressure Test located in Diagnosis and Testing of WSM, Section 303-03C. Does the vehicle exhibit a coolant leak at the coolant pump?
 - (1). Yes - proceed to Step 4.
 - (2). No - this article does not apply. Refer to PC/ED Manual or WSM for normal diagnostics.
4. Replace the coolant pump. Refer to WSM, Section 303-03C.

© 2018 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.