

# Technical Service Bulletin

#### 64 Door window automatic lowering or raising inoperative

64 18 56 2050080/2 June 18, 2018. Supersedes Technical Service Bulletin Group 64 number 18-49 dated January 19, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A5, A5 Cabriolet, and A5 Sportback	2017 - 2018	All	Not Applicable

#### **Condition**

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised header data (Corrected Elsa display issue)		
1	01/19/2018	Initial publication		

#### **Customer states:**

• Intermittently the door window does not slightly roll down when opening the door, or does not roll up when closing the door.

## **Technical Background**

Updated control module software.

## **Production Solution**

New software in the driver door control module, J386 (address word 0042) or the front passenger door control module, J387 (address word 0052) addressed the condition.

### **Service**

#### **SVM Update Instructions**

1. Follow all instructions in TSB 2011732: 00 Software Version Management (SVM), operating instructions.



# Technical Service Bulletin

2. Update the driver door control module, J386 (address word 0042) or the front passenger door control module, J387 (address word 0052) using the SVM action code as listed in the table below, if necessary:

Model	Control Module Address	Hardware Part Number	Software Part Number	Original Software Version	New Software Version	SVM Code Input
A5, A5 Cab, and A5 Sportback A5 Sportback	0042	4M0959793H 4M0959793F	4M0959793F	128 (or lower)		42A014
	0052	4M0959792H 4M0959792F	4M0959792F		129	
	00BB 00BC	4M0959795 (E/H) 8W0959395 (E/H) 8W0959595 (E/H)	4M0959795 (C/F) 8W0959395 ("/F) 8W0959595 ("/F)			

3. Perform basic settings of the windows

## **Warranty**

Claim Type:	<ul> <li>110 up to 48 Months/50,000 Miles.</li> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> </ul>			
	If vehicle is outside any warranty, this Technical Service Bulletin is informational only.			
Service Number:	6438			
Damage Code:	0039			
Labor Operations:	Software Update	0151 0000	Time stated on diagnostic protocol (Max 100 TU)	
Diagnostic Time:	ic Time: GFF No allowance		0 TU	
	Road test prior to service procedure	No allowance	0 TU	



# Technical Service Bulletin

	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2050080/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

#### **Additional Information**

The following Technical Service Bulletin will be necessary to complete this procedure:

• TSB 2011732, 00 Software Version Management (SVM), operating instructions.

All part and service references provided in this TSB (2050080) are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.