

July 2018 Technical Service

# **S55 - CHECK CONTROL MESSAGE: DRIVE FAULTY**

#### MODEL

F80 (M3 Sedan)	F82 (M4 Coupe)	F83 (M4 Convertible)	
			1

#### SITUATION

Check Control Message (CCM) "Drive faulty" is display for 5 seconds

The reduced engine power message may briefly illuminate.

The following fault codes may be stored in the Digital Motor Electronics (DME):

- 20A503 exhaust turbocharger coolant pump: signal implausible
- 20A203 charge air cooling system: signal implausible

#### CAUSE

An error in the DME software causes misdiagnosis of the coolant pump signals

### CORRECTION

Reprogram vehicle with ISTA 4.12.3x or higher

### PROCEDURE

For conditions that are similar to the situation described:

- 1. Perform diagnosis with the latest version of ISTA.
- 2. Program the vehicle using **ISTA 4.12.3x** or higher.

Model	Target integration level
F80 (M3 Sedan)	F020-18-07-530 or higher
F82 (M4 Coupe)	
F83 (M4 Convertible)	

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

#### Always connect a BMW-approved battery charger/power supply (SI B04 23 10).

For information on programming and coding with ISTA, refer to CenterNet / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

## PARTS INFORMATION

Parts replacement will not provide a solution to this situation.

#### WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

Defect Code:	1042315900	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2/AIR	Performing "vehicle test" (with vehicle diagnosis system – checking faults) (Main work)
Or:		
00 00 556	Refer to KSD2/AIR	Performing "vehicle test" (with vehicle diagnosis system – checking faults) (Plus work)
And:		
61 21 528	Refer to KSD2/AIR	Connect an approved battery charger/power supply (indicated in KSD2 as "Charging battery")
And:		
61 00 730	Refer to KSD2/AIR	Programming / encoding control unit(s)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006.

Refer to KSD2/AIR for the corresponding flat rate unit (FRU) allowances.

During the same workshop visit, if a vehicle also requires another Technical Campaign or repair that also includes programming and encoding the control units, the programming procedure may only be invoiced one time.

#### Vehicle Programming and Encoding

A. The programming procedure automatically reprograms and encodes all vehicle control modules which do not have the latest software i-level. If one or more control module failures occur "during" this programming procedure:

• Please claim this "consequential" control module-related repair work under the defect code listed in this bulletin with the applicable KSD2/AIR labor operations.

Please explain this additional work (The why and what) on the repair order and in the claim comments section.

B. For control module failures that occurred "prior" to performing this programming procedure:

• When "covered" under an applicable limited warranty, claim this control module-related repair work using the applicable defect code and labor operations (including diagnosis) in KSD2/AIR.

[ Copyright ©2018 BMW of North America, Inc. ]