
TIS Service Bulletin Page 1 of 2



July 2018 **Technical Service** 

# FALSE WARNINGS THAT THE FRONT PASSENGER SEAT IS OCCUPIED WITHOUT THE SEAT BELT BUCKLED

New information provided by this revision is preceded by this symbol UPDATED.



This Service Information bulletin supersedes SI B72 04 17 dated February 2018

#### What's new:

- Model: Adding G01 and G32 and end of production date
- · Cause: Modify the cause
- · Correction: Adding video for new location
- Procedure information: Update the attached procedure for a new information.

### UPDATE! MODEL

G12 (7 Series)	G30 (5 Series)	G32 (6 Series Gran Turismo)	G01 (X3)
----------------	----------------	-----------------------------	----------

Vehicles produced to March 2018

#### SITUATION

Acoustic and visual warnings indicate that the front passenger seat is occupied and the seat belt is not fastened, when the seat is actually unoccupied.

If the situation is currently present, sit in the seat and move the seat to a different position then the POL (Passenger Occupancy Light) light will function correctly.

## UPDATE! CAUSE

- 1. Electronics (for example smart phones or laptops) are connected to the USB charging port or cigarette lighter and placed on the seat.
- 2. Faulty plug connection to Evaluation Electronics (CIS).
- 3. Unsecured seat harness under the seat.

## 


- Secure the loose cables between the CIS seat mat and CIS Evaluation Electronic.
- · Check the POL operation after repair.
- Install 2 cables tie on the seat wiring harness as shown in this video: https://tinyurl.com/V520218

## PROCEDURE

TIS Service Bulletin Page 2 of 2

For conditions that are similar to the situation described and the problem is not currently present:

1. Verify with customer that no objects were lying on the seat that could have caused the warnings.



phones, etc., could cause the front passenger airbag to activate.

This behavior occurs primarily with devices that are connected to the vehicle electrical system via a USB cable or other charger adapter.

In vehicles with an acoustic seat belt warning, this could cause the warning signal to sound.

Moisture on the seat surface can also cause a faulty seat occupancy detection; refer to SI B65 04 14.

2. If step 1 does not identify the cause of the warnings, then follow the attached procedure to repair the Passenger Occupancy Detection Error condition.

### **UPDATES PARTS INFORMATION**

Part Number	Description	Quantity
61 13 8 377 065	Cable tie	2

### **WARRANTY INFORMATION**

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	6577081400		
Labor Operation:	Labor Allowance:	Description:	
65 99 000	4 FRU	Work time to secure the CIS cable under the seat (Main work)	
Or:			
65 99 000	2 FRU	Work time to secure the CIS cable under the seat (Plus work – Vehicle is already in the workshop)	

Posted: Tuesday, July 17, 2018

#### **ATTACHMENTS**

View PDF attachment <a href="mailto:B720417\_Repair\_Procedure">B720417\_Repair\_Procedure</a>.

[ Copyright ©2018 BMW of North America, Inc. ]

# PASSENGER OCCUPANCY DETECTION ERROR CORRECTION



- 1. Move the front seat to its highest position.
- 2. Detach the lower front seat trim.
- 3. Disconnect the Evaluation Electronics (CIS) plug connection.




- 4. Check the plug for conditions resulting in possible poor electrical connection corrosion, bent pins, etc. removing control unit if needed, as shown.
- 5. Repair any connection problems.
- 6. Securely re-install control unit, if removed.
- 7. Reconnect plug into CIS.





8. Secure the loose clip attached to cables, as shown.

SI B72 04 17Attachment



- 10. Re-attach seat trim panel.
- 11. Verify free motion of seat belt and seat adjustment.
- 12. Verify correct operation of occupant detection system. There should be no fault memory entries for airbag warnings.
- 13. Check the POL function