



Technical Service Bulletin

40 Rumbling/creaking noises from front of vehicle while driving

40 18 83 2048266/3 July 30, 2018. Supersedes Technical Service Bulletin Group 40 number 17-75 dated September 20, 2017 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017 - 2018	All	Not Applicable
A6, A7, and A8	2015 - 2018	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Warranty</i> (Updated Labor Operations)
2	09/20/2017	Revised <i>Warranty</i> (Updated Labor Operations)
1	07/13/2017	Initial publication

Customer states:

- They can hear rumbling, squeaking, creaking or similar noises from the front of the vehicle while driving on uneven roads. The noises can possibly be heard and felt in the footwell or behind the dash panel.

Workshop findings:

- The noises can be reproduced.

Technical Background

The noises can be generated on the lower left control arm in the area of the hydro-bushing.

Parts such as the coupling rod (4M0411317), axle components, and shock absorbers/air suspension struts are replaced often by mistake.



Technical Service Bulletin

Production Solution

Modified hydro-bushing in control arm link (Figure 1):

- A6/A7 - 4G4HN011283 on 06/21/2016, part number 4G0407183B
- A8 - 4H7HN000731 on 06/01/2016, part number 4H0407183C
- Q7 - 4M2GD063812 on 04/29/2016, part number 4M0407183B




Figure 1. Hydro-bushing.

Service

The noises from the guide link can be transmitted into the vehicle interior through the connection of the subframe on the body. As a result, the noises can be heard in the footwell.

Check the lower guide link of the front axle as it may be the source of the noises. If necessary, replace the hydro-bushing on the guide link.


The following steps are helpful in diagnosing the source of the noises:

1. Does the noise get louder when steering?
2. Do you perceive the concern in the footwell while driving on uneven roads or over speed bumps?
3. Does the concern only occur with minor unevenness of the road?



Tip: Please precisely locate the source of the noise with acoustic testers. A replacement of the guide link is not effective.

If the cause of the noise cannot be traced to mounting of the guide link, continue analysis on other components. Relaxing the front axle while there is weight on the wheels in many cases improves the situation.



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	4016		
Damage Code:	0020		
Labor Operations:	A6 and A7:		
	1 Replace guide link mounting	4012 5550	30 TU
	1 Lower guide link remove + reinstall	4016 1950	70 TU
	1 Wheel remove + reinstall	4405 1900	20 TU
	Replace 2 guide link mountings	4012 5650	50 TU
	2 Lower guide links remove + reinstall	4016 2050	100 TU
	2 Wheels remove + reinstall	4405 2000	30 TU
	A8:		
	1 Lower guide link remove + reinstall (Includes time to replace 1 guide link mounting)	4016 1950	70 TU
	1 Wheel remove + reinstall	4405 1900	20 TU
	2 Lower guide links remove + reinstall (Includes time to replace 2 guide link mountings)	4016 2050	100 TU
	2 Wheels remove + reinstall	4405 2000	30 TU
	Q7:		
	1 Replace guide link mounting	4012 5550	30 TU
	1 Lower guide link remove + reinstall	4016 1900	90 TU
	Replace 2 guide link mountings	4012 5650	50 TU
	2 Lower guide links remove + reinstall	4016 2000	140 TU



Technical Service Bulletin

Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2048266/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Please refer to ETKA for the correct part information.

Additional Information

All parts and service references provided in this TSB (2048266) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.