



LTB01200NAS1

TECHNICAL BULLETIN

21 JUN 2018

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

415-01: Information and Entertainment Systems

SUBJECT/CONCERN:

Front Door Speaker Distortion/Vibration

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery Sport (LC)	2015-2017	501001-634067	Halewood
Range Rover Evoque (LV)	2015	955857-999999	Halewood
Range Rover Evoque (LV)	2015-2017	000051-158730	Halewood

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

Distortion/vibration may be evident from a front door speaker.

CAUSE:

This may be caused by the door speaker material.

ACTION:

Should a customer express this concern, follow the Workshop Procedure below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
LR096616	Front door speaker	2
LR001790	Front door trim clip	10
LR013135	Front door trim clip	22

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission

system to obtain the latest repair time.

- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Speaker - Front door - Replace - Pair	86.50.89.60	0.6	42	LR079254

NOTE:

Normal Warranty procedures apply.

SERVICE INSTRUCTION:

- 1 Confirm the cause of the customer concern (See TOPIx Workshop Manual section 415-01: Information and Entertainment Systems - Diagnosis and Testing - Speakers - Pinpoint Test C).
 - If a replacement speaker **is not** required, do not continue with this Workshop Procedure.
 - If a replacement speaker **is** required, go to step 2.
- 2 Replace the front left door speaker (see TOPIx Workshop Manual section 415-01: Information and Entertainment System - Front door speaker).
 - Repeat this step for the front right door speaker.