

ATTENTION:
 GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2018 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2017-2019MY Impreza
 2018-19MY Crosstrek
 2018-19MY Legacy and Outback
 2019MY WRX and WRX STI
 2019MY Ascent
 2018-19MY BRZ

NUMBER: 15-220-18R
DATE: 03/08/18
REVISED: 09/05/18

SUBJECT: Harman Audio / Infotainment: Troubleshooting
 Apple CarPlay and Android Auto Connectivity Concerns

INTRODUCTION:

This bulletin provides troubleshooting steps to use when diagnosing concerns of the Apple CarPlay and / or Android Auto feature not connecting or launching properly when a compatible device is connected to the head unit.


SERVICE PROCEDURE / INFORMATION:

- 1) Confirm the condition as reported by the customer. Information located in the Harman Investigation Guide-Questionnaire may be required to understand fully how to duplicate the condition. The customer’s phone will most likely also be required unless a similar phone is available for testing.
- 2) Verify the device being used is compatible with the head unit by checking the listings on Subaru.com under Bluetooth Compatibility using the following link:
<https://www.subaru.com/owners/index.html>
- 3) Verify the cable being used to connect the device is a OEM (e.g. Apple, Samsung, Motorola, etc.) -supplied or a certified OEM / Manufacturer-compliant product.
- 4) Verify the software version of the head unit and if it is not the most current, update it using the most recent version available. See TSB 15-211-17R for the complete Service Procedure to update the head unit software if needed.
- 5) Confirm the device’s operating system; CarPlay (iOS) or Android Auto (OS) versions are up to date.

Continued...


<p>CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.</p>	<p>Subaru of America, Inc. is ISO 14001 Compliant</p>
<p>Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.</p>	<p>ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.</p>

- 6) Confirm the CarPlay or Android Auto feature is enabled on the device without any Restrictions by following the steps below:



For Apple CarPlay:

- Confirm Restrictions have been disabled by going to: **Settings > General > Restrictions**. If the slider is green as shown in the illustration below, CarPlay is NOT restricted (CarPlay is operational).
- If the slider is to the left (slider is gray), CarPlay is restricted. Either move the slider to the right (green) or press Enable Restrictions (you may be required to create / use a password to use the Enable Restrictions function).



For Android Auto:

Confirm the Android Auto feature on the device is set to accept new car connections.

- Open **Android Auto > Open the Menu on the top left > Settings > Connected Cars**
- Enable “Add new cars to Android Auto” by moving the slider to the right as shown in the image to the left.

- 7) If the N/G condition persists after performing the instructions supplied in steps 1-6 above, try using another known-good certified OEM / Manufacturer-compliant connecting cable in the customer’s vehicle to rule out a faulty connecting cable. If the N/G condition persists, the connecting cable is likely to be OK.
- 8) Try the device and (confirmed OK) connecting cable in a known good vehicle.
- 9) If CarPlay / Android Auto launches and operation is OK, swap the USB hub / cable from the known good vehicle into the customer vehicle and check for proper operation. If OK, replace the USB hub / cable.

Continued...

10) If the N/G persists, swap the head unit with a known good one and if a faulty head unit is identified, replace it using the Harman exchange unit program.

IMPORTANT CAUTION: Always disconnect the Telematics Data Communication Module (DCM) BEFORE any swapping of head units. DCMs must NEVER be swapped or the customer's services will not function and DCM replacement may be required to resolve.

11) If the above steps do not resolve the customer's concern with CarPlay/ Android Auto function, complete a fresh Harman Investigation Guide- Questionnaire documenting the customer's concern and the results of each diagnostic step in this bulletin. If possible, capture a video of the condition then contact the SOA Techline to review for next steps. Techline will request you send the completed questionnaire, step by step bulletin results and any videos of the condition.

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Classic or Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code	H/U Type
HARMAN APPLE CARPLAY & ANDROID AUTO TROUBLESHOOTING	A031-161	1.0	ZRM-43	Base
			ZRN-43	Plus / Mid
			ZRO-43	High (w/ Navi)

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.