

**Campaign code.**L62X-A.04.18**Campaign description.**Wheel badge upgrade**Model.**Huracan Performante Coupè and Spyder**Model year.**2018**Special or Limited Versions.**Only with central single nut with standard wheel badge;
(no carbon fibre).**Markets.**All.**VIN identification**From JLA06599 to JLA09015**Warning:** before starting with the repair, log to the Warranty portal and check through VIN Info:

- The vehicle is effectively involved by these bulletin instructions; some cars may not be included even when they are in the VIN range.
- The procedure identified by a letter (e.g. A, B or C...etc. whose differences are explained below in this bulletin), taking care to order and use the parts corresponding to the assigned procedure.

Example

VIN	17 DIGIT VIN	Model	MODEL NAME	Warranty Start Date	DD/MM/YYYY	Warranty End Date	DD/MM/YYYY	
Total days of workshop repairs: 0								
Prior activated CPO list								
CPO /	Validity months	Classification	Mileage	Insertion date	Approval date	Start date	Expire date	Claim status
Page 1 of 0 Rows								
Available Campaigns								
Campaign Code	Campaign Type	Procedures	Campaign Description	Campaign Starting Date	PDF	AV		
LXXA-XXXX	A - Service Action	B	CAMPAIGN NAME	DD/MM/YYYY				

**Note**

Procedure A will be available only when the instructions require to carry out a preliminary control to determine whether or not a vehicle needs to be updated.

Information to the field

As a result of the continuous monitoring of the product, Automobili Lamborghini Spa introduced a new O-rings of increased hardness and a hole on the hubcaps to prevent accidental loss of the hubcaps.

Field solution

The instruction herein detailed describes two procedures:

- B, which concerns the installation of a new O-ring.

Spare parts.

Order the following part number which are connected to the operation required:

- Operation B – O-ring installation.

P/N	Description	Q
470698009	O-ring	4

Replaced parts management.

Store properly and tagged the parts replaced with bar code form for their identification during Area Manager visits.

Labour time

- O-ring installation + Wheel badge drilling: 0.2 h.


Substituted former Bulletins.

None.

Warranty Claim instructions

To claim the reimbursement log into the warranty system management on the Lamborghini Portal and consults the manual “W.Claim “ available on the portal for the download .

Select the desired campaign and go on with the claim insertion, read carefully the windows message content and choose the option button corresponding to the operation performed .



On the base of the chosen option the reimbursement will be:

- OPTION B, O-ring installation and wheel badge drilling:
manpower: 0,2h.
spare parts: 470698009.



Remember to fill all data in the section “Service and Recall Campaign” in the Warranty booklet of the vehicle as shown below.

[illegible]

Wait until the brake discs have cooled down completely!



This procedure can be used on both the right and the left sides.




Be very careful not to damage the wheel hub cover or the wheel rim.

1. Remove the wheel hub cover.



**B. Installation of new O-ring.**


2. Remove the old O-ring, pulling in the direction of the arrow.




3. New configuration (wheel badge without O-ring).

**C. Drilling of the wheel badge.**

4. Follow the technical drawing specifications to make the 2 holes ($\varnothing 1,5$ mm) in the correct position of the badge (Space A in the figure).




5. To find the correct position of the holes Automobili Lamborghini recommend using the circled point in the image as a reference (in order to obtain two alligned holes). Using like a reference the circled point in the figure and mark the 2 points where you will need to drill the holes.

**WARNING**

The points must be marked in the space A (see image below).




6. Make the holes in the two points marked.




ATTENTION

To avoid damaging of the badge, be careful not to touch the points shown in the following figure during the drilling operation.



D. Installation of the new O-ring in the wheel badge.

7. Install the new O-ring (part number 470698009) in the space B (see the figure), pushing in the direction of the arrow.



E. Reinstall

8. To reinstall the wheel hub cover, follow the removal procedure in reverse order.