

L73X-
A.03.18

To:
Subject:
Date:
Pages

Official After Sales Network
Wheel badge upgrade
March 9, 2018
4



Campaign code.

L73X-A.03.18

Campaign description.

Wheel badge upgrade

Model.

1) Aventador Coupe and Roadster; 2) Aventador S Coupe and Roadster.

Model year.

From 2016 to 2018

Special or Limited Versions.

1) Only with central single nut with standard wheel badge; (no carbon fibre); 2) Centenario.

Markets.

All.

VIN identification

From GLA03099 to JLA07150

Warning: before starting with the repair, log to the Warranty portal and check through VIN Info:

- The vehicle is effectively involved by these bulletin instructions; some cars may not be included even when they are in the VIN range.
- The procedure identified by a letter (e.g. A, B or C...etc. whose differences are explained below in this bulletin), taking care to order and use the parts corresponding to the assigned procedure.

Example

VIN	17 DIGIT VIN	Model	MODEL NAME	Warranty Start Date	DD/MM/YYY	Warranty End Date	DD/MM/YYY	
Total days of workshop repairs: 0								
Prior activated CPO list								
CPO	Validity months	Classification	Mileage	Insertion date	Approval date	Start date	Expire date	Claim status
⏪ ⏩ Page: 0 of 0 Rows: 0 ⏴ ⏵								
Available Campaigns								
Campaign Code ▾	Campaign Type	Procedures	Campaign Description	Campaign Starting Date	PDF	AV		
LXX-A-XXXX	A - Service Action	B	CAMPAIGN NAME	DD/MM/YYYY				



Note

Procedure A will be available only when the instructions require to carry out a preliminary control to determine whether or not a vehicle needs to be updated.

Information to the field

As a result of the continuous monitoring of the product, Automobili Lamborghini Spa introduced a new O-rings of increased hardness and a hole on the hubcaps to prevent accidental loss of the hubcaps.

Field solution

The instruction herein detailed describes two procedures:

- B, which concerns the installation of a new O-ring.

Spare parts.

Order the following part number which are connected to the operation required:

- Operation B – O-ring installation.

P/N	Description	Q
470698009	O-ring	4

Replaced parts management.

Store properly and tagged the parts replaced with bar code form for their identification during Area Manager visits.

Labour time

- O-ring installation + Wheel badge drilling: 0.2 h.


Substituted former Bulletins.

None.

Warranty Claim instructions

To claim the reimbursement log into the warranty system management on the Lamborghini Portal and consults the manual “W.Claim “ available on the portal for the download .

Select the desired campaign and go on with the claim insertion, read carefully the windows message content and choose the option button corresponding to the operation performed .



On the base of the chosen option the reimbursement will be:


- OPTION B, O-ring installation and wheel badge drilling:
manpower: 0,2h.
spare parts: 470698009.

[illegible]



B. Installation of new O-ring.

- Remove the old O-ring, pulling in the direction of the arrow.




- New configuration (wheel badge without O-ring).



C. Drilling of the wheel badge.

- Follow the technical drawing specifications to make the 2 holes ($\varnothing 1,5$ mm) in the correct position of the badge (Space A in the figure).



- To find the correct position of the holes Automobili Lamborghini recommend using the circled point in the image as a reference (in order to obtain two alligned holes). Using like a reference the circled point in the figure and mark the 2 points where you will need to drill the holes.




WARNING

The points must be marked in the space A (see image below).




6. Make the holes in the two points marked.



ATTENTION

To avoid damaging of the badge, be careful not to touch the points shown in the following figure during the drilling operation.



D. Installation of the new O-ring in the wheel badge.

7. Install the new O-ring (part number 470698009) in the space B (see the figure), pushing in the direction of the arrow.



E. Reinstall

8. To reinstall the wheel hub cover, follow the removal procedure in reverse order.