

<b>Reference</b>	SSM73950
<b>Models</b>	Discovery / L462 Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	Unable to reset service interval using Pathfinder
<b>Category</b>	Electrical
<b>Last modified</b>	05-Jul-2018 00:00:00
<b>Symptom</b>	206000 Warning Indicators
<b>Content</b>	<p><b>Issue:</b> Technician unable to reset service interval on Instrument Cluster using Pathfinder following an oil service on 18MY non Plug-in Hybrid Electric Vehicles and non Hybrid Electric Vehicles only.</p> <p><b>Cause:</b> Gateway Module software not transferring data between modules during service reset routine.</p> <p><b>Action:</b> Using Pathfinder with P170 or later loaded, re-configure the existing Gateway Module followed by the service interval reset procedure.</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>