Reference	SSM73945
Models	Discovery Sport / L550
Title	17MY L550 HVAC SWDL fails
Category	Diagnostic Software Hardware
Last modified	27-Jul-2018 00:00:00
Symptom	000101 Diagnostic Concerns
Content	<u>lssue:</u>
	When performing a software update on the HVAC (Heating Ventilation and Air Conditioning Control Module) the update fails stating SDD (Symptom Driven Diagnostics) has failed to resolve software.
	Cause:
	The module acronym within the As Built data doesn't match the acronym used by SDD when resolving software.
	 Action: Restart the JLR Approved Diagnostic Equipment Select 'Manual Patch' Icon on the Application Launcher screen. Make sure that both Symptom Driven Diagnostics (SDD) and PATHFINDER are closed before opening the Manual Patch downloader. A pop-up will be displayed for Manual Patch downloader Enter 'MP_JLR_G0010' in the Patch Name field. Select 'Start'. The Manual Patch downloader will then download the manual patch. When the patch download has completed, a message will be displayed, asking the user to confirm that the application can run the manual patch. Select 'Yes'. When complete, the following message will be displayed: 'Successfully downloaded and started manual patch. Please make sure that the patch has installed successfully.' NOTE: This message will end after 10 seconds. Start a new diagnostic session. Complete the required HVAC programming Close the session. Restart the JLR Approved Diagnostic Equipment.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

- 1 = Poor Basic information provided The SSM does not help me resolve the customer concern.
- 3 = Average Adequate information provided The SSM partially helps me resolve the customer concern.
- 5 = Excellent All required information provided to resolve the customer concern.