

Noise Symptom - Brake Axle Brake Squeal (I-no. 1KR/1KV): Replacing rear disc brake pads (SY 37/18)

Vehicle Type: **Cayenne basic model (9YA)**

Model Year: **As of 2018**

Equipment: I-no. 1KR (18" brake caliper, green)
I-no. 1KV (18" brake caliper, black)

Subject: **Rear disc brake pads**

Symptom: If the vehicle is braked while driving at low speeds, a squealing noise can be heard shortly before the vehicle comes to a standstill.

Cause: The disc brake pads can cause the squealing noise due to a change in the manufacturing process used by the supplier.

Remedial Action: In the event of a customer complaint, replace the existing rear disc brake pads with the disc brake pads with the part number ⇒ 9Y0.698.451.K (or a higher index, see Porsche Spare Parts Catalog), see ⇒ *Workshop Manual '463856 Replacing rear disc brake pads'*.

Date of Introduction: Modified rear disc brake pads have been installed during production since anuary 22, 2018.

Parts Info: **9Y0.698.451.K** ⇒ Disc brake pads

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
46385600	Replacing rear disc brake pads	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	46380	Rear disc brake pad
Damage type (SA4)	2019	squealing

References: ⇒ *Workshop Manual '463856 Replacing rear disc brake pads'*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2018 Porsche Cars North America, Inc.