

**Symptom - Body Exterior - Difficult To Refuel The Vehicle (I-no. 0K3): Replacing fuel tank (SY 111/18)**

Vehicle Type: **All Panamera 4/Turbo S/Sport Turismo/Turbo S Sport Turismo (971) Hybrid Models**

Model Year: **As of 2017 up to 2018**

Equipment: **Hybrid drive system PHEV (I-no. 0K3)**

Subject: **Fuel tank**

Symptom: Customers complain that it is difficult to refuel their vehicle and the refuelling process keeps stopping and starting.

Cause: Problems can occur during refuelling because a control valve (in the fuel tank) is not engaged completely.

Remedial Action: In the event of a customer complaint, replace the fuel tank, see ⇒ *Workshop Manual '201019 Removing and installing fuel tank (Hybrid)'*.

Date of Introduction: Since April 19, 2018 or as of chassis number 97 ZJL 17 5108, the fuel tanks that are produced are increasingly being checked to ensure that the control valves are engaged correctly.

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
20101920	Removing and installing fuel tank	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	20100	Fuel tank
Damage type (SA4)	1634	problems refuelling

References: ⇒ *Workshop Manual '201019 Removing and installing fuel tank (Hybrid)'*

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2018 Porsche Cars North America, Inc.