

# Technical Service Bulletin

#### 20 Fuel cannot be added to vehicle or fueling vehicle is difficult

20 18 04 2044039/5 August 15, 2018. Supersedes Technical Service Bulletin Group 20 number 18-01 dated April 30, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017 - 2018	All	Not Applicable

### **Condition**

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised Warranty (Added Labor Operation)
4	04/30/2018	Revised header data (Included all Q7)
3	04/26/2018	Revised header data (Added model years)

#### **Customer states:**

• Vehicle does not accept fuel, is slow to refuel, or it is difficult to insert the fuel pump nozzle.

## **Technical Background**

There is a broken flap inside of the filler neck (Figure 1).




Figure 1. Broken flap inside of filler neck.



# Technical Service Bulletin

### **Production Solution**

Improved flap design of the filler neck.

### **Service**

Replace complete fuel tank according to the instructions in Elsa at Repair Manual, *Power Unit >> Fuel Supply >> Fuel tank >> Removing and installing fuel tank.* 



#### Note:

- If suspension alignment is necessary, upload alignment protocol before and after repair to Doc-IT.
- Alignment protocols must be retained for warranty claim payment. Failure to do so will result in non-payment of the claim.

## **Warranty**

Claim Type:	• 110 up to 48 Months/50,000 Miles.			
	G10 for CPO Covered Vehicles – Verify Owner.			
	If vehicle is outside any warranty, this Technical Service Bulletin is informational only.			
Service Number:	2010			
Damage Code:	0010			
Labor Operations:	Fuel tank remove + reinstall	2010 1950	280 TU	
	Fuel tank replace	2010 5550	70 TU	
	Rear axle remove + reinstall (For vehicles without adaptive air suspension)	4205 1900	480 TU	
	Rear axle remove + reinstall (For vehicles with adaptive air suspension)	4205 1901	370 TU	
	Wheel alignment check	4495 0300	90 TU	
	Front wheel track adjusted (If necessary)	4488 1550	20 TU	



# Technical Service Bulletin

	Front wheel camber adjusted (If necessary)	4489 1550	40 TU
	Rear wheel track adjusted (If necessary)	4493 1550	30 TU
	Rear wheel camber adjusted (If necessary)	4494 1550	30 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 60 TU)
	Road test before procedure	No allowance	0 TU
	Road test after procedure	0121 0002	10 TU
Claim Comment:	As per TSB # 2044039/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## **Required Parts and Tools**

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.			
Part Number	Part Description	Quantity	
See ETKA	Fuel Tank	01	
See ETKA	Fasteners, Bolts, Nuts and Screws as needed per the Repair Manual	See ETKA/ELSA	

## **Additional Information**

All parts and service references provided in this TSB (2044039) are subject to change and/or removal.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.