



JTB00651NAS1

TECHNICAL BULLETIN

08 OCT 2018

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

419-00

SUBJECT/CONCERN:

Auto Stop/Start Inhibit Icon Incorrectly Displayed While Driving

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	APPLICABILITY:
F-TYPE (X152)	2019	K55804-K57079	V6 S/C 3.0L Petrol /V8 S/C 5.0L Petrol

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

The Auto Stop/Start inhibit icon may be incorrectly displayed on the Instrument Cluster (IC) while driving the vehicle.

CAUSE:

This may be caused by a CCF (Car Configuration File) software error.


ACTION:

Should a customer express this concern, follow Diagnostic Procedure below.


PARTS:

No Parts Required

TOOLS:



Jaguar Land Rover-approved Midtronics battery power supply



Jaguar Land Rover-approved diagnostic equipment with latest PATHFINDER software

WARRANTY:

- NOTES:**
- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
 - The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Car Configuration File (CCF) - Update	86.99.94	0.2	04	T2H26342

NOTE:
Normal Warranty procedures apply.

DIAGNOSTIC PROCEDURE:

- CAUTIONS:**
- A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle startup battery.
 - All ignition ON/OFF requests MUST be performed; failure to do these steps may cause damage to vehicle control modules.

1 Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle startup battery.

2 **NOTE:**
The Jaguar Land Rover-approved diagnostic equipment must be loaded with PATHFINDER version 193 (or later).

Connect the Jaguar Land Rover-approved diagnostic equipment to the vehicle and begin a new session.

3 **NOTE:**
The Jaguar Land Rover-approved diagnostic equipment will read the correct Vehicle Identification Number (VIN) for the current vehicle and automatically take the vehicle out of Transit mode (if required).

Follow all on-screen instructions.

4 Select **Service**.

5 Select **Select CCF**.

6 Select **Copy from AS BUILT**.

- 1 Follow the on-screen instructions until the application finishes successfully.
-

7 Exit the current session.

- 1 If required, reset the vehicle to **Transit mode**.
 - 2 Select the **Exit** icon.
-

8 Disconnect the diagnostic equipment and battery power supply from the vehicle.