

Service

Category Audio/Visual/Telematics

Section	Navigation/Multi Info Display	Market USA	Toyota Supports
---------	-------------------------------	------------	-----------------

#### Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2018 - 2019	Camry, Camry HV, Mirai, Sienna	

#### SUPERSESSION NOTICE

The information contained in this bulletin supersedes Service Bulletin No. T-SB-0285-17.

- Applicability has been updated to include 2019 model year Camry and Camry Hybrid vehicles and 2018 2019 model year Mirai and Sienna vehicles.
- The entire bulletin has been updated.

Service Bulletin No. T-SB-0285-17 is obsolete and any printed versions should be discarded.

#### Introduction

Some 2018 model year Camry and Camry Hybrid vehicles equipped with Entune<sup>™</sup> 3.0 Audio Plus (version 1004 or earlier) or Entune<sup>™</sup> 3.0 Premium Audio (version 1000 or earlier) may exhibit one or more of the following conditions:

- Abnormal display operation in the destination screen after "IG-ON"
- Abnormal turn-by-turn direction operation
- Inaccurate traffic information displays
- Abnormal navigation routing
- Abnormal destination and ETA operation while navigation is operating
- Abnormal rerouting operation
- Abnormal navigation operation after "IG-OFF/ON" cycle
- Navigation will not avoid areas that have been set to avoid
- Intermittent rebooting
- Navigation will not set from Destination Assist

### Introduction (continued)

- Navigation will intermittently not boot up after "IG-ON"
- Abnormal operation when selecting unplayable songs from the USB flash drive
- Abnormal screen appearance
- Abnormal music browsing when manually browsing music
- Apps take a long time to load
- Abnormal shuffle function when listening to iPhone
- Voice output for temperature is incorrect unit
- Rebooting when connecting an Apple® device with more than 501 podcasts
- Abnormal brightness of Entune<sup>™</sup> apps
- Voice recognition inoperative
- Delay after answering a phone call
- Incoming call continues to ring (unable to answer or decline)

Some 2018 model year Camry and Camry Hybrid vehicles equipped with Entune<sup>™</sup> 3.0 Audio Plus (version 1006) or Entune<sup>™</sup> 3.0 Premium Audio (version 1003) or earlier may exhibit one or more of the following conditions:

- Intermittent rebooting
- Error message when searching for street address that does not exist
- Abnormal voice recognition operation
- Abnormal iPod source operation
- iPod song list is slow to load
- Unable to authorize Remote Services via head unit app
- Scout is displayed in app catalog Entune<sup>™</sup> Premium Audio
- Abnormal time changes in the middle of the time zone
- Abnormal Home screen operation
- Scout causes the phone to disconnect and not reconnect
- "Voice recognition is currently initializing and is not available at this time" message appears after every key cycle.

#### Introduction (continued)

Some 2018 model year Camry and Camry Hybrid vehicles equipped with Entune <sup>™</sup> 3.0 Audio Plus (version 1011) or Entune <sup>™</sup> 3.0 Premium Audio (version 1011) or earlier may exhibit one or more of the following conditions:

- Entune<sup>™</sup> disconnects after Destination Assist Call
- Intermittent rebooting
- CDs cannot be skipped
- Song library voice recognition cannot be used with 300 albums or 3,500 songs
- Abnormal on-screen message appears intermittently
- List selection when only one Point of Interest (POI) is available
- Abnormal screen freeze
- Abnormal music playback/song played frequently on shuffle
- Sound output from phone instead of car speakers
- Intermittent black screen
- Incorrect name displays on incoming phone call
- Freeway exit list does not match the current highway
- Remaining distance does not decrease
- Freeway exit list defaults on after key cycle
- Directional arrows display multiple times
- Unable to reorder multiple destinations

### Introduction (continued)

Some 2018 – 2019 model year Camry, Camry Hybrid, Mirai, and Sienna vehicles equipped with Entune<sup>™</sup> 3.0 Audio Plus (version 1030) or Entune<sup>™</sup> 3.0 Premium Audio (version 1030) or earlier may exhibit one or more of the following conditions:

- Exit list does not match the current highway
- Intermittent freezing
- Abnormal navigation turn arrow operation
- Intermittent rebooting
- Unable to search categories of POIs using voice recognition
- Slow GPS reception during Pre-Delivery Inspection (PDI)
- Abnormal tire change information operation
- Distance remaining does not decrease
- Abnormal map display
- Freeway exit list defaults on after key cycle
- Unable to reorder destinations

A software update is now available to address these conditions. Follow the Software Update Procedure in this bulletin to update the software.

### Warranty Information

OP CODE	DESCRIPTION	MODEL	TIME	OFP	T1	T2
EL1702	Software Update	Camry, Camry HV	0.3	86140-33A70 86140-33390 86140-06450 86140-06490 86140-06500 86140-06870 86140-06880 86140-06890 86140-06A00 86140-06A10 86140-06A20 86140-06A30 86140-06A30 86140-06A40 86140-06A90 86840-06010 86840-06011 86840-06012	87	74
		Mirai		86140-62010		
		Sienna		86140-08100 86140-08110 86140-08080 86140-08090 86840-06013		

#### APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

### Software Update Information

MODEL	HEAD UNIT		SOFTWARE UPDATE FILE
Camry, Camry HV	Entune™ 3.0 Audio Plus	DCU	<u>17TDT1NA-DA00_0015.kwi</u>
Camry,	Entune™ 3.0 Premium Audio	DCU	<u>17TDT2NA-DA00_0015.kwi</u>
Camry HV, Mirai, Sienna		MEU	<u>17TMT2NA-DA00 0017.kwi</u>

#### MULTIMEDIA SOFTWARE FILE DOWNLOAD

The Multimedia software update file(s) may be downloaded directly from this Service Bulletin by clicking on the applicable file name(s) in the table above. Once downloaded, the file(s) may be copied directly to a commonly available blank USB flash drive.

For Entune<sup>™</sup> Premium Audio, be sure to copy both the DCU and the MEU files to the USB flash drive.

For USB flash drive requirements and download instructions: Refer to *TIS* – *Diagnostics* – *Reprogramming* – *Reference Documents* – <u>*Multimedia Software Download Instructions*</u>.

#### Software Update Procedure

- 1. Start the engine.
- 2. Press the Menu button on the radio faceplate, then select Setup.



### Software Update Procedure (continued)

3. Select General on the Setup screen.



4. Scroll down and select Software Update.

### Figure 3.

Setup	12:47	Z
<li>General</li>	Driver Setting	\$
Bluetooth	Delete Personal Data	
♪ Audio	Software Update	
D Phone	Software Update Setting	
wź Voice	Gracenote Database Update	
~	Software Information	*

5. Verify that the software version is the same or earlier as indicated in the Introduction.

#### Figure 4.

Software Update	12	:49	
Model ID DCU Model ID MEU	17TDT2NA-DA00 17TMT2NA-DA00	) D	C,
	Current	New	
Audio	: XXXX	-	$\approx$
Navigation	: XXXX	-	
			$\approx$
Model Info	History	Update Soft	ware

### Software Update Procedure (continued)

6. If the software needs to be updated, download the software from the Software Update Information section onto an empty USB flash drive.

If "IG-OFF" occurs, repeat steps 1 – 4 to reenter the Software Update screen.	NOTE	
	If "IG-OFF" occurs, repeat steps 1 – 4 to reenter the Software Update screen.	

7. Insert the prepared USB flash drive into the vehicle's USB port.

### Figure 5.

Software Upda	te 1	2:49	8
Model ID DCU Model ID MEU	17TDT2NA-DA 17TMT2NA-DA	00	C
1	lew software was fo	und.	
Navigation	: 1000	XXXX	)     
Model Info	History	Update Sof	tware

8. Verify that the NEW software is up to date on the Software Update screen.

### Table 1. Software Version Information

TYPE -	ENTUNE™ 3.0 AUDIO PLUS		ENTUNE™ 3.0 PREMIUM AUDIO	
	CURRENT VERSION	NEW VERSION	CURRENT VERSION	NEW VERSION
Audio	1004 1006 1011 1030	1040	1000 1003 1011 1030	1040
Navigation	_	-	1030	1042

9. Press the Update Software button in the lower right-hand corner.

#### Figure 6.

Software Updat	te 1	2:49	8
Model ID DCU Model ID MEU	17TDT2NA-DA 17TMT2NA-DA	00 .00	5
	Current	New	
Audio	: 1000	XXXX	$\approx$
Navigation	: 1000	XXXX	
			$\approx$
Model Info	History	Update Soft	tware

### Software Update Procedure (continued)

10. Select OK on the Software Update Detail screen.

### Figure 7.

Software Update Detail	12:53	0
Audio Software Fixed. Navigation Software Fixed.	ت ج	
	*	
	OK	)

11. Select Agree on the Terms of Service screen.

#### Figure 8.

Terms of Service	1:01	Z
Various bug fixes.		¢
		*
		*
Agree	Disagree	

12. Select Yes on the "Would you like to start the software update?" pop-up.

### Figure 9.

Terms of Service	1:01				
The new software is XXX MB.					
Would you like to	start the software update?				
Would you like to s Yes	start the software update? No				

#### Software Update Procedure (continued)

13. Once the head unit begins installation, the update will take about 10 minutes.



### NOTE

- Do NOT turn off the engine or ACC before the software is ready for updating.
- Do NOT pull the USB flash drive out of the vehicle USB port before the software is ready for updating.
- 14. When the message "The software is ready for updating" appears, turn OFF the ignition.

#### Figure 11.

Software Update	1:07	2
The software is	ready for updating.	
Please park your car at a safe loca complete the update.	ation and turn the engine off and o	n to

- 15. Turn the ignition ON to complete the software update.
- 16. Once the software update has completed, remove the USB flash drive.

#### Software Update Procedure (continued)

 Perform steps 1 – 4 to verify that the software version matches the current Software Version Information table below.

Software Update	12	12:49		
Model ID DCU Model ID MEU	17TDT2NA-DA00 17TMT2NA-DA00		¢.	
	Current	New		
Audio	: XXXX	-	$\approx$	
Navigation	: XXXX	-	 	
Model Info	History	Update Sof	tware	

#### **Table 2. Software Version Information**

ТҮРЕ	ENTUNE™ 3.0 AUDIO PLUS		ENTUNE™ 3.0 PREMIUM AUDIO	
	CURRENT VERSION	NEW VERSION	CURRENT VERSION	NEW VERSION
Audio	1040	_	1040	
Navigation	_		1042	_