

## Field Service Bulletin Trucks

Date Group No. Release Page 11.2018 **284 069 01** 1(6)

Exhaust Particulate Sensor, Repair 2017 Models VNL, VNM, VHD

# FSB 284-069, Exhaust Particulate Sensor, Repair (2017 Vehicles)

(November 2018)

Some trucks built between 1/1/2017 and 11/15/2017 may experience a Particulate Matter (PM) Sensor fault that can result in the MIL lamp illuminating. These faults may be P24DA, "PM Sensor Exhaust Sample Error," or P24D1, "PM Sensor Regen Incomplete." These faults may be caused by contamination of the PM sensor. In order to reduce the likelihood of sensor contamination, new exhaust pipe parts are being made available that contain an internal water management feature along with an integrated drain that will prevent contamination of the sensor. If either of these two faults occur, follow the instructions outlined in this bulletin to clean the exhaust pipes and install a new exhaust pipe with the new contamination prevention measures.

Service personnel: Please circulate, read and initial

Service Manager	Warranty Adminis- trator	Workshop Foreman	Service Technicians						

PV729-FSB284-069 V USA142168012

## Required Parts - All Years

Inspect and replace the v-band clamp as needed

A new gasket will be needed when disconnecting the SCR exit.

Note: No gasket needed for vertical SCR.

Part Description	Part Number		
SCR Gasket	21095726		
V-band Clamp	21021850		
Particulate Matter Sensor	22946032		


**Note:** Customer adaptations can change required parts. Check for adaptations before ordering parts.

#### Parts List-2017 Vehicles

Model	Cab Type	Exhaust Configuration	Pipe 1	Flex Pipe	Clamp (Qty will vary)
VNL	Day Cab	Single Outlet Right Side Outboard	23190647	N/A	N/A
VHDAxle Fwd	Day Cab	Single Outlet Right Side Outboard	23155762	N/A	N/A
VNM VHDAxle Bwd	Day Cab	Single Outlet Right Side Outboard	23155772	23154829	20961913
VHDAxle Bwd	Day Cab	Dual Outlet	23155774	N/A	N/A
VHDAxle Fwd	Day Cab	Dual Outlet	23155785	23154829	20961913
VNM VHD VNL	Sleeper Cabs	Single Outlet Right Side Outboard Dual Outlet	(Not Bright) 23154798 (Bright) 23154799	N/A	N/A

#### Instructions

1 Decommission the vehicle. Install wheel chocks and disconnect the battery.



- 2 Remove the PM sensor and module.
- 3 Remove all exhaust pipes up to the SCR outlet pipe.
- 4 Pressure wash the inside of each pipe that will be reused.
- 5 Reassemble the exhaust system using the new parts referenced in the table above.
- 6 Mark the SCR outlet pipe 1.5" from the end also mark the new pipe (not flex) 1.5" from its inlet.
- 7 Slip the flex pipe as for over the SCR outlet pipe as possible.
- 8 Install the new exhaust pipe.
- 9 Using a new clamp assemble the new exhaust pipe to the new flex pipe using the 1.5" mark to get the correct amount of overlap.
- 10 Slide the assembly into place using the 1.5" mark on the SCR outlet as a reference point and to ensure the correct amout of overlap, once in both pipes are in place use clamps to secure.

**Note:** Correct installation is achieved when the flex pipe is in a "relaxed" state, there should be no compression or expansion visible on oposing sides of the pipe after installed.

11 Install the new PM sensor and module.

**Note:** Do not use any lubricant of any kind on the PM sensor threads.

Note: Align the tab on the sensor with the slot.

12 Torque the sensor to 35 +/- 5 Nm (26+/- 4 Ft lb)

13 Install the sensor module.

14 Torque the nuts to

M6: 10 +/- 5 Nm (88 +/- 3 in lb) M8: 24 +/- 4 Nm (17.1 +/- 3 ft lb)

15 Install the wire ties and clamps.


Date 11.2018 Group **284** 

No. **069**  Release 01

Page 4(6)


Note: Use high temperature cable ties.

#### 16 Connect the battery.



W3086758

- 17 Clear any DTC codes.
- 18 Remove the wheel chocks.



W7086759

Date 11.2018 Group **284** 

No. **069**  Release 01

Page 6(6)

#### Reimbursement

This repair may be eligible for reimbursement if a product failure was experienced within time and mileage limits of the applicable Warranty coverage.  Reimbursement is obtained via the normal claim handling process.	UCHP Reimbursement		
Claim Type (used only when uploading from the Dealer Bus. Sys.)	W		
Labor Code			
Primary Labor Code (Exhaust Particulate Sensor, Repair)	2846-16-09-01 See table for times.		
Causal Part	22946032		

## **Labor Times Reference – 2017 Vehicles**

Model	Cab Type	Exhaust Configuration	Pipe 1
VNL VNM VHD	Day Cab	Single Outlet Right Side Outboard	1.5
VHD	Day Cab	Dual Outlet	2.9
VNM VHD VNL	Sleeper Cabs	Single Outlet Right Side Outboard Dual Outlet	3.5