

Service

Category Vehicle Interior

Section Interior Panels/Trim Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
2018 - 2019	Camry, Camry HV		

Introduction

Some 2018 – 2019 model year Camry and Camry Hybrid vehicles with brushed aluminum or gray metallic trim may exhibit a condition where the instrument panel LH and RH outside register assemblies reflect upon the side window glass. Alternative outside register assemblies with a gloss black finish have been developed to reduce this condition. Follow the Repair Procedure in this bulletin to reduce this condition.

Figure 1. Brushed Aluminum Trim



Figure 3. Gloss Black Trim



Figure 2. Gray Metallic Trim



TOYOTA T-SB-0129-18 October 10, 2018 Page 2 of 14

Instrument Panel Trim Reflection

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
BD1801	R & R LH and RH Instrument Panel Register Assemblies	0.6	55650-06480 55650-06481 55670-06520-E2 55670-06521-E2 55670-06531-E1 55670-06860-B0 55670-06530-B0 55670-06531-B0 55670-06531-B0 55650-33440 55650-33500 55670-33320-E3 55670-33430-E0 55670-33430-B0 55670-33430-B1	67	31

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Parts Information

Table 1. LH Outside Register Assembly

			PART NUMBER					
GRADE	TRIM COLOR	IM COLOR PREVIOUS NEW COLOR		PREVIOUS		COLOR	PART NAME	QTY
		NAP	CBU	NEVV				
All	Brushed Aluminum	55650-06480	55650-33440	55650-33580 – Register /	_	_	Register Assy,	1
	Metallic Gray	55650-06481	55650-33500		instrument Paner No. 1			

TOYOTA T-SB-0129-18 October 10, 2018 Page 3 of 14

Instrument Panel Trim Reflection

Parts Information (continued)

Table 2. RH Outside Register Assembly

			PART NUMBER					
GRADE	TRIM COLOR	PREV	'IOUS	NEW	COLOR	PART NAME	QTY	
		NAP	CBU	INEAA				
L, LE	Brushed Aluminum	55670-06520-E2	55670-33320-E3	FF070 22400 F0	55670-33490-E0	Layered		
L, LL	Metallic Gray	55670-06521-E2	55670-33430-E0	33070-33490-20	Wood			
XLE	Brushed Aluminum	55670-06530-E1	- N/A	55670-33500-E0 Tiger Eye	Tiger Eye			
\LL	Metallic Gray	55670-06531-E1	IVA	33070-33300-20	nger Lye	Register Assy,	1	
SE	Brushed Aluminum	55670-06860-B0	55670-33320-B0	55670 22400 PO	Micro	No.3	'	
SE	Metallic Gray	55670-06861-B0	55670-33430-B1	55670-33490-B0 Square Metal				
XSE	Brushed Aluminum	55670-06530-B0	N/A	55670-33500-B0	Textured			
\\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	Metallic Gray	55670-06531-B0	TV/A		Metal			

Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
Plastic Pry Tool Set*	00002-06000-01	1

^{*} Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.



Page 4 of 14


Instrument Panel Trim Reflection

Repair Procedure

Disassembly

- 1. Remove the No. 1 meter hood cluster.
 - A. Apply protective tape to the area shown in the figure.


Figure 4.



1 Protective Tape

B. Disengage the three clips as shown in the figure.

Figure 5.




1-3	Dis engagement Order
4	Hand Placement Location

Repair Procedure (continued)

Disassembly (continued)

C. Disengage the four clips and three guides as shown in the figure.

Figure 6.



1-7	Disengagement Order
8	Hand Placement Location


D. Disconnect the connector to remove the No. 1 meter hood cluster.

Repair Procedure (continued)

Disassembly (continued)

- 2. Remove the No. 2 instrument panel garnish sub-assembly.
 - A. Disengage the five clips as shown in the figure.


Figure 7.



1 – 5	Dis engagement Order
6	Hand Placement Location

B. Disengage the six clips as shown in the figure to remove the No. 2 instrument panel garnish sub-assembly.

Figure 8.




1 – 6	Dis engagement Or der
7	Hand Placement Location

Repair Procedure (continued)

Disassembly (continued)

- 3. Remove the No. 3 instrument panel register assembly.
 - A. Disengage the eight clips as shown in the figure.


Figure 9.



1-8	Dis engagement Order
9	Hand Placement Location

B. Disengage the three clips as shown in the figure to remove the No. 3 instrument panel register assembly.

Figure 10.



1-3	Dis engagement Order
4	Hand Placement Location

C. If the vehicle is equipped with illumination, disconnect the connector.

Repair Procedure (continued)

Disassembly (continued)


- 4. Remove the front door scuff plate LH.
 - A. Disengage the claw as shown in the figure.

HINT

Use the same procedure for the front and rear sides.


B. Disengage the eight claws and one guide as shown in the figure to remove the front door scuff plate LH.

Figure 11.




Hand Placement Location

Figure 12.



- 5. Remove the cowl side trim sub-assembly LH.
 - A. Remove the clip.
 - B. Disengage the claw and clip as shown in the figure to remove the cowl side trim sub-assembly LH.

Figure 13.




6. Disconnect the forward portion of the front door opening trim weatherstrip LH.

Repair Procedure (continued)

Disassembly (continued)

- 7. Remove the instrument side panel LH.
 - A. Apply protective tape to the area shown in the figure.


Figure 14.



1 Protective Tape


B. Using a plastic pry tool, disengage the two claws and four clips as shown in the figure.

Figure 15.



C. Disengage the three guides as shown in the figure to remove the instrument side panel LH.

Figure 16.






Repair Procedure (continued)

Disassembly (continued)


- 8. Remove the No. 1 instrument panel under cover sub-assembly.
 - A. Remove the two screws.

Figure 17.




B. Disengage the three claws as shown in the figure.

Figure 18.



C. Disengage the guide as shown in the figure.

Figure 19.



D. Disconnect the connector.



Repair Procedure (continued)

Disassembly (continued)

- E. Disengage the two claws as shown in the figure to disconnect the DLC3 connector.
- F. Disengage the two clamps as shown in the figure to remove the No. 1 instrument panel under cover sub-assembly.

9. Disengage the three clips as shown in the figure to remove the No. 2 meter hood cluster.

Figure 20.





Figure 21.




Repair Procedure (continued)

Disassembly (continued)


10. Disengage the claw and two guides as shown in the figure to disconnect the hood lock control lever sub-assembly.

Figure 22.



11. Disengage the six clips as shown in the figure to remove the No. 1 instrument panel sub-assembly.

Figure 23.






Repair Procedure (continued)

Disassembly (continued)

12. Disengage the four clips as shown in the figure to remove the No. 1 instrument panel garnish sub-assembly.


Figure 24.



Hand Placement Location

13. Disengage the two clips and claws as shown in the figure to remove the No. 1 instrument panel register assembly.

Figure 25.



Hand Placement Location




Repair Procedure (continued)

Reassembly


 Engage the two clips and claws to install the NEW No. 1 instrument panel register assembly.

Figure 26.



- 2. Install the NEW No. 3 instrument panel register assembly.
 - A. If the vehicle is equipped with illumination, connect the connector.
 - B. Engage the 11 clips to install the No. 3 instrument panel register assembly.

Figure 27.



- 3. Reassemble the vehicle in reverse order of disassembly.
- 4. Confirm the condition is reduced.