ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the hoxes provided, right.





SUBARU

NUMBER: 04-24-18

DATE: 11/09/18

SERVICE BULLETIN

APPLICABILITY: 2012-2016MY Impreza 2.0

2013-2017MY Crosstrek 2014-2017MY Forester

SUBJECT: Increased Steering Effort when Cold, DTC C2532

INTRODUCTION:

This bulletin announces a new Electronic Power Steering (EPS) control module for the models listed above. These new EPS control modules address a limited number of customer concerns regarding increased steering effort which may occur during freezing temperatures after a cold start. The cause has been identified as a frozen relay contact inside the control module. Illumination of the EPS warning lamp can also occur and a DTC C2532 may be stored.

PRODUCTION CHANGE INFORMATION:

The new EPS control modules were incorporated into production per the table below:

Model	Starting VIN		
Crosstrek	HH276440		
Forester	JH401989		

PART INFORMATION:

Description	Part Number	Applicability		
CONTROLLER- STEERING	34710FJ002	- Impreza		
	34710FJ113			
	34710FJ212			
	34710FJ252			
	34710FJ032			
	34710FJ083	- Crosstrek		
	34710FJ241			
	34710FJ201			
	34710FJ212			
	34710FJ252			
	34710SG102	Forester		
REMINDER: Always order the most up-to-date steering controller part number for the specific VIN of the vehicle being repaired.				

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

Bulletin Number: 04-24-18; Date: 11/09/18

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

The service procedures for diagnosing and replacement of the EPS control module remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time. This includes but is not limited to: important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair.

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Classic or Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code
EPS CONTROL UNIT R&R	B659-021	0.2	UJF-43
EPS TESTING & DIAGNOSIS	C659-011	0.5	UJF-43

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 04-24-18; Date: 11/09/18 Page 2 of 2