

Technical Information

121/18ENU WJ61

Service

5


WJ61 - Checking Filler Flap and Replacing it if Necessary (Workshop Campaign)

Model Line:	Panamera (971)
Model Year:	As of 2017 up to 2019
Subject:	Filler flap
Information:	There is a possibility that the required clearance of the filler flap with respect to the body side panel is not guaranteed under all conditions due to unfavorable tolerances.
	As a result, the filler flap may be difficult to open and close.
Remedial Action:	Check filler flap and replace it if necessary.
Affected Vehicles:	Only the vehicles assigned to the campaign (see also PIWIS Vehicle information). This campaign affects 9,228 vehicles in North America.

5 Service WJ61 ENU 121/18

Installation

position:



Installation position of filler flap

1 – Filler flap

Parts required

Parts Info: Please note: Dealers will receive initial allocation of 6 of the required Non-Hybrid Filler Flap part number (00004330428). If additional parts needed before next allocation, please order if necessary by emailing recallrelease@porsche.us.

All Hybrid Charge Port Door parts (00004330429) must be ordered if necessary by emailing recallrelease@porsche.us.

No parts are required for checking the filler flap.

Parts required if the filler flap has to be replaced:

Part No.	Designation	Qty.
00004330428	\Rightarrow Filler flap	1 ea. (only if required)

Expendable items:

Materials required for **painting** the filler flap:

Paint in vehicle color*

* For warranty processing, enter the Part No. **WJ610000001**, with the "expendable items" designation as an **additional part** in the warranty claim.

This includes all materials used for the entire area for the respective labor operation (including masking materials, sanding materials and cleaning agents as well as paint in vehicle color). For details, see \Rightarrow *Technical Information 'Warranty processing'*.

Required tools

Tools:

- Steel rule (or locally available equivalent tool)
- Feeler gauge, 0.80 mm (or locally available equivalent tool)

Checking filler flap

Information Prerequisite for checking the filler flap:


The filler flap can be opened and closed properly

If this is **not** possible, the filler flap must be **replaced**. A further check is not required in this case. Please document the fact that the filler flap cannot be opened or closed properly by attaching digital photos or a video in PQIS. For instructions for replacing the filler flap, see \Rightarrow *Technical Information 'Replacing filler flap'*.

Work Procedure: 1 Check projection between the filler flap and rear side panel in the locking mechanism area.


Pay particular attention to the following points:

Check the filler flap using a steel rule and feeler gauge with the filler flap fully closed
 ⇒ Checking filler flap.



Checking filler flap


- Make sure not to scratch the paint surface when using the steel rule.
- Position the steel rule at the center at the same height as the locking mechanism as shown
 ⇒ Checking filler flap with the edge on the filler flap.
- Make sure that the steel rule is completely touching the filler flap, particularly in the rear area ⇒ Checking projection of filler flap -arrow A-.



Checking projection of filler flap

- Do not put pressure on the steel rule.
- Use a 0.80-mm feeler gauge because the required projection of the filler flap with respect to the side panel must be at least 0.80 mm.
- Push in the feeler gauge at the steel rule directly after the body gap between the filler flap and side panel and check the projection at this point ⇒ Checking projection of filler flap -dimension X-.
- Repeat the check at least twice. To do this, position the steel rule slightly above and below the original test position at the same height as the locking mechanism and check the projection again there.
- Required projection value: The projection from filler flap to side paneldirectly after the body gap between the filler flap and side panel must be greater than or equal to 0.80 mm (\$\Rightarrow Projection of filler flap -dimension X-).

Tachnical Information	Service	
Technical Information	121/18enu WJ61	51 D



Projection of filler flap

• Document the results of the check. To do this, attach digital photos in PQIS showing the projection of the filler flap and the check performed using the feeler gauge.

Subsequent procedure, depending on the result of the check:

- The projection is greater than or equal to 0.80 mm at all previously checked positions: The filler flap does not have to be replaced. Continue with Step 2.
- The projection is less than 0.80 mm at one of the previously checked positions: Replace the filler flap. For instructions, see *⇒ Technical Information 'Replacing filler flap'*.
- 2 Enter the campaign in the Warranty and Maintenance booklet.

End of remedial action.

For warranty processing, see **Scope 1** under \Rightarrow *Technical Information 'Warranty processing'*.

Replacing filler flap

- 1 Open the flap \Rightarrow *Removing flap* -2-.
- 2 Release catch \Rightarrow *Removing flap*-1- using a suitable tool and pull off the filler flap \Rightarrow *Removing flap*-2- (\Rightarrow *Removing flap*-arrow-).
- 3 Paint new filler flap \Rightarrow *Removing flap* -2- in vehicle colour.

i Information Painting stage S1 - new part painting

The painting of new body parts - including sub-parts and sections - is referred to as "new part painting". A differentiation is made between screwed parts and welded parts.

The painting of visible and invisible interior surfaces, e.g. the lid hinge, is classified as Painting stage 1.

Stage 1 includes:


- Phase I Preparation
- Phase II Priming
- Phase III Painting
- Phase IV Applying clear lacquer

Information on painting can be found in the "Paint Manual - Painting method for plastic components".

- 4 Carefully push new filler flap/charge port door \Rightarrow *Removing flap*-2- into the guides until it locks with an audible click.
- 5 Carry out a function test on the filler flap. To do this, close the flap and then open it again.
- 6 Close the flap.
- 7 Enter the campaign in the Warranty and Maintenance booklet.

End of remedial action.

For warranty processing, see **Scopes 3 - 4** under \Rightarrow *Technical Information 'Warranty processing'*.



Removing flap

Warranty processing

Scope 1:

Scope 2:

Scope 3:

•	Porsche dealerships that carry out this campaign fully must submit an invoice for the relevant scope from scopes 1 or 3 .		
•	Porsche dealerships that hand the filler flap over to an external service provic out the required painting work must submit an invoice for Scope 4 . In this cas a copy of the invoice in PQIS.	-	
Ch	necking projection between filler flap and side panel		
•	The filler flap does not have to be replaced		
14	Vorking time:		
vv	-		
	hecking projection between filler flap and side panel	Labor time: 21 T	

• All work required for replacing the filler flap was carried out fully by the Porsche dealership

Working tir	ne:			
Replacing filler flap Labor time: 154 T Includes: Checking projection between filler flap and side panel Removing and installing filler flap Painting filler flap in vehicle color			Labor time: 154 TU	
Parts required:				
000043304	428	Filler flap	1 ea.	
WJ6100000	201*	Expendable items (masking materials, sanding materials and cleaning agents, paint in vehicle color)	1 ea. (for warranty invoicing only)	
* For warranty processing, enter the Part No. WJ610000001 with the "expendable items" designation as an additional part costing \$13.50 USD in the warranty claim.				
\Rightarrow Damage Code WJ61 066 000 2				

Scope 4: Checking projection between filler flap and side panel - Replacing filler flap

The filler flap was painted by an external service provider

Working ti	me:		
Replacing filler flapLabor time: 24Includes:Checking projection between filler flap and side panel Removing and installing filler flap			Labor time: 24 TU
Parts requ	ired:		
000043304	428	Filler flap	1 ea.
WJ610000	201*	Expendable items (masking materials, sanding materials and cleaning agents, paint in vehicle color)	1 ea. (for warranty invoicing only)
Sublet labo	or:		
Painting fille	r flap in ve	hicle color	Sublet labor time: max. 130 TU
	5.	sing, enter the Part No. WJ610000001 with the "e. al part costing \$13.50 USD in the warranty claim.	xpendable items" desig-
⇒ Damage	e Code W.	J61 066 000 2	

Scopes 5 - 10: Only relevant for Hybrid vehicles – see relevant Technical Information for these vehicle types

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.